



LotNo	1140006	LOCATION	HAKATA-S*
MAKER	YANMAR	YEAR	2007
MODEL	VIO20-3	HOURL	7783
S/N	34865B		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	3TNV76-P
	S/N	45694
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	YES / あり
	NOTE	INJECTION PUMP GOVERNOR ROD OIL LEAK / 噴射ポンプガバナロッド油洩れ

FRONT ATTACHMENT	BOOM	TYPE	SWING
		SWING BRACKET LOOSE / スイングブラケットガタ	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	SLIDE DOWN BY ITSELF / 自然降下 (SEVERELY / 大)	
	PINS	BOOM	OK
		ARM	OK
BUCKET		LOOSE / ガタ	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD	OK	
	250 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	-	
	TRACK ROLLER	LEFT SIDE LOOSE / 左側にガタ	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	DRIVING MOTOR'S FRAME IS DAMAGED WITH A HOLE. / 走行モーターフレーム部穴あき破損	

CAB/CNP	CAB/CNP	CORROSION/腐食
	ROPS	NO / なし
	SEAT	TORN / 破れ
	CONTROL LEVER	2nd GEAR PEDAL MALFUNCTION / 走行2速ペダル戻り不良
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	WIRE FOR THE BLADE LEVER SOMETIMES MALFUNCTIONS./ブレードレバー用ワイヤー戻り時々不具合 LEFT LEVER-BOX GAS SPRING FAILURE / 左レバーボックスガススプリング不良

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました