



GREEN AUCTION

| | | | |
|-------|---------|----------|----------|
| LotNo | 1133008 | LOCATION | HAKATA-S |
|-------|---------|----------|----------|

| | | | |
|-------|---------|-------|------|
| MAKER | KUBOTA | YEAR | 2013 |
| MODEL | U-20-3S | HOURL | 4497 |
| S/N | 15640 | | |

MINI EXCAVATOR

133th Internet Auction 2025/09/18 ~ 2025/09/19

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

| | | |
|--------|---------|--------------------|
| ENGINE | MODEL | - |
| | S/N | - |
| | COOLANT | OK |
| | OIL | OK |
| | START | OK |
| | BLOW-BY | YES/あり(SLIGHTLY/小) |
| | NOISE | NO/なし |
| | EPA | NO/なし |
| | NOTE | |
| | | |

| | | | |
|---------------|--------------------------------|------|----------------------|
| UNDERCARRIAGE | SHOE | TYPE | RUBBER |
| | <input type="checkbox"/> W/PAD | | |
| | 250 mm | | CRAWLER CUT. クローラー切れ |
| | PIN BUSH | OK | |
| | CARRIER ROLLER | OK | |
| | TRACK ROLLER | OK | |
| | FRONT IDLER | OK | |
| | SPROCKET | OK | |
| | NOTE | | |
| | | | |

| | | | |
|------------------|--------|--------|----------------------|
| FRONT ATTACHMENT | BOOM | TYPE | SWING |
| | | OK | |
| | ARM | TYPE | STD |
| | | OK | |
| | PIPING | OK | |
| | BUCKET | TYPE | STD |
| | | OK | |
| | BLADE | OK | |
| | PINS | BOOM | LOOSE/ガタ |
| | | ARM | LOOSE/ガタ |
| | | BUCKET | LOOSE SEVERELY/ガタ大きい |
| | NOTE | | |

| | | |
|---------|---------------|---------|
| CAB/CNP | CAB/CNP | OK |
| | ROPS | NO/なし |
| | SEAT | TORN/破れ |
| | CONTROL LEVER | OK |
| | A/C OR HEATER | - |
| | COMPUTER | OK |
| | MONITOR | OK |
| | BATTERY | OK |
| | NOTE | |
| | | |

| | | |
|-----------|--------|----------------------|
| CYLINDERS | BOOM | OK |
| | SWING | ROD SCRATCHED/ロッド傷あり |
| | ARM | OK |
| | BUCKET | ROD SCRATCHED/ロッド傷あり |
| | BLADE | OK |
| | NOTE | |

| | |
|------------|---------------------|
| TURN TABLE | LOOSE LATERALLY/横ガタ |
|------------|---------------------|

| | | |
|---------|----------------|---|
| CONTROL | HYDRAULIC PUMP | MINOR OIL LEAK / オイルにじみ |
| | TRAVEL | OK |
| | SWING | OK |
| | CONTROL | OK |
| | NOTE | CONTROL VALVE MINOR OIL LEAKING. コントロールバルブ 油にじみ |

| | |
|------------|---|
| ATTACHMENT | - |
|------------|---|

REMARK

NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP. 在来船輸出の場合は要洗車

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました