



GREEN AUCTION

| | | | |
|-------|-------------|----------|------------|
| LotNo | 2133005 | LOCATION | YOKOHAMA-E |
| MAKER | CATERPILLAR | YEAR | 2009 |
| MODEL | 308DSR | HOURL | 5624 |
| S/N | JPS00210 | | |

EXCAVATOR

133th Internet Auction 2025/09/18 ~ 2025/09/19

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

| | | |
|--------|---------|-----------------------------|
| ENGINE | MODEL | 4M40 |
| | S/N | HL4679 |
| | COOLANT | OK |
| | OIL | OK |
| | START | OK |
| | BLOW-BY | NO/なし |
| | NOISE | NO/なし |
| | EPA | YES/あり |
| | NOTE | MINOR OIL LEAKING SLIGHTLY. |
| | | |

| | | | |
|---------------|--------------------------------|------|-------|
| UNDERCARRIAGE | SHOE | TYPE | STEEL |
| | <input type="checkbox"/> W/PAD | OK | |
| | 450 mm | | |
| | PIN BUSH | OK | |
| | CARRIER ROLLER | OK | |
| | TRACK ROLLER | OK | |
| | FRONT IDLER | OK | |
| | SPROCKET | OK | |
| | NOTE | | |
| | | | |

| | | | |
|------------------|--------|---------------------------|-------------|
| FRONT ATTACHMENT | BOOM | TYPE | STD,OFF-SET |
| | | OK | |
| | ARM | TYPE | STD |
| | | OK | |
| | PIPING | - | |
| | BUCKET | TYPE | STD |
| | | OK | |
| | BLADE | TURNED UP/めくれ(UPPER,LEFT) | |
| | PINS | BOOM | OK |
| | | ARM | OK |
| | | BUCKET | OK |
| | NOTE | | |

| | | |
|---------|---------------|---|
| CAB/CNP | CAB/CNP | OK |
| | ROPS | NO/なし |
| | SEAT | OK |
| | CONTROL LEVER | NOT COOL/冷えない |
| | A/C OR HEATER | OK |
| | COMPUTER | OK |
| | MONITOR | OK |
| | BATTERY | DEAD/あがり |
| | NOTE | NOT WORKING WITHOUT EXTERNAL BATTERY.. ABLE TO CHARGE BATTERY. バッテリーをつながないと動かない 少し充電すれば動く |
| | | |

| | | |
|-----------|--------|-------------------------|
| CYLINDERS | BOOM | OK |
| | SWING | - |
| | ARM | OK |
| | BUCKET | OK |
| | BLADE | MINOR OIL LEAK / オイルにじみ |
| | NOTE | |

| | |
|------------|----|
| TURN TABLE | OK |
|------------|----|

| | | |
|---------|----------------|----|
| CONTROL | HYDRAULIC PUMP | OK |
| | TRAVEL | OK |
| | SWING | OK |
| | CONTROL | OK |
| | NOTE | |

| | |
|------------|---|
| ATTACHMENT | - |
|------------|---|

REMARK

1.7t HOOK

NEAR RIGHT SIDE COVER DENT. BOOM FOOT HOSE INTERFERE WITH BOOM CYLINDER PIPING. TEMPORARY FIXING BY TIE. 右サイドカバー付近へこみあり ブーム根本ホースがブームシリンダーの配管にひっかかる。現状タイラップでまてめている。

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました