



GREEN AUCTION

LotNo	1136009	LOCATION	HAKATA-S
-------	---------	----------	----------

MAKER	KUBOTA	YEAR	2007
MODEL	U-40-5	HOURL	808
S/N	70501		

MINI EXCAVATOR

136th Internet Auction 2026/01/29 ~ 2026/01/30

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	-
	S/N	-
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES/あり(SLIGHTLY/小)
	NOISE	NO/なし
	EPA	NO/なし
	NOTE	ENGINE MINOR OIL LEAKING. エンジンに油にじみ箇所あり

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD		
	400 mm		CRAWLER CUTS. クローラー切れあり
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	MINOR OIL LEAK / オイルにじみ(LEFT 4, RIGHT 1)	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	LEFT SIDE TRAVEL MOTOR COVER MINOR OIL LEAKING. STAIN. NEED WASHING. 左走行モーターカバー油にじみあり 汚れあり 要洗車注意	

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	OK	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	LOOSE/ガタ
		ARM	LOOSE/ガタ
		BUCKET	LOOSE/ガタ
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO/なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

CYLINDERS	BOOM	MINOR OIL LEAK / オイルにじみ
	SWING	OK
	ARM	OK
	BUCKET	ROD SCRATCHED/ロッド傷あり
	BLADE	OK
	NOTE	

TURN TABLE	LOOSE LATERALLY/横ガタ
------------	---------------------

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

NAME PLATE MISSING. HOUR UNCERTAIN. 銘板欠品 アワー不確実

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました