



LotNo	1260011	LOCATION	KOBE-N
MAKER	CATERPILLAR	YEAR	2019
MODEL	314FCR	HOUR	3143
S/N	RAF10707		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	-
	S/N	-
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING		OK
	BUCKET	TYPE	STD
			OK
	BLADE		-
	PINS	BOOM	OK
		ARM	OK
	BUCKET	OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	-
	ARM	OK
	BUCKET	OK
	BLADE	-
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	4WAY MULTI LEVER / 4WAYマルチレバー

ATTACHMENT	-
------------	---

REMARK	2.9TON ARM CRANE / クレーン CRANE SENSOR MISSING / クレーンセンサー欠損 THE MOVEMENT OF THE BOOM UP IS ABNORMAL. / ブーム上げ動作がスムーズでない。ひっかかる。 NEED WASHING / 要洗車
--------	---

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD		
	500 mm	WORN / 摩耗	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	LITTLE BENT / 曲がり(小)
	A/C OR HEATER	OK
	COMPUTER	CRANE MODE NG / クレーンモード不可
	MONITOR	OK
	BATTERY	DEAD / あがり
NOTE	FRONT GUARD STRUCTURE IS BENT AND IS TOUCHING THE BOOM CYLINDER. / フロントガード曲がり、ブームシリンダーに接触する	

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました