



# GREEN AUCTION

LotNo	1140012	LOCATION	HAKATA-A*
-------	---------	----------	-----------

## MINI EXCAVATOR

140th Internet Auction 2026/05/21 ~ 2026/05/22

MAKER	HITACHI	YEAR	1995
MODEL	EX25-2	HOUR	5646
S/N	1AP-01803		

 DOCUMENT/書類
  UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	D1105
	S/N	-
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES/あり(SLIGHTLY/小)
	NOISE	NO/なし
	EPA	NO/なし
	NOTE	OIL PAN SEEPING. オイルパンにじみ

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			TIP DENT/先端へこみ
	PIPING		OK
	BUCKET	TYPE	STD,SLOPE. NARROW
			OK
	BLADE		EDGE CRACKED/エッジ割れ
	PINS	BOOM	LOOSE SEVERELY/ガタ大きい
		ARM	LOOSE/ガタ
	BUCKET	LOOSE/ガタ	
NOTE	SWING BRACKET LOOSE SEVERELY. スイングブラケットガタ大		

CYLINDERS	BOOM	OIL LEAKING /油漏れ
	SWING	OIL LEAKING /油漏れ
	ARM	OIL SEEPING. /油にじみ
	BUCKET	OK
	BLADE	OK
	NOTE	HYDRAULIC HOSE DETERIORATED. 油圧ホース劣化

TURN TABLE	LOOSE LATERALLY/横ガタ
------------	---------------------

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

### REMARK

COVER DENT, CORRODED. NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP. カバー類へこみ 腐食あり 在来船輸出の場合は要洗車

UNDERCARRIAGE	SHOE	TYPE	RUBBER
			<input type="checkbox"/> W/PAD
			300 mm
			SCRATCHED/キズあり
	PIN BUSH		OK
	CARRIER ROLLER		OK
	TRACK ROLLER		OK
	FRONT IDLER		OK
	SPROCKET		OK
	NOTE		

CAB/CNP	CAB/CNP	-
	ROPS	-
	SEAT	TORN/破れ
	CONTROL LEVER	LOWER LEVER OIL SEEPING. レバ下部油にじみ
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	TRAVEL SPEED SWITCHING DEFECT. SAFETY LEVER DEFECT. 走行速度切替不良 セーフティレバー不良

### ATTENTION/注意

\*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました