GREEN AUCTION

MANLIFT

LotNo	8146002	LOCATION	YOKOHAMA-E

MAKER	AICHI	YEAR	2004				
MODEL	SR21A	HOUR	—	CARRIER HR	—	CARRIER KM	—
S/N	683082	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不動車

ENGINE

	CARRIER	CRANE
MODEL	4JG1	—
S/N	250070	—
COOLANT	OK	—
OIL	OK	—
START	OK	—
BLOW-BY	NO / なし	—
NOISE	NO / なし	—
NOTE	EPA	

HYDRAULIC (CRANE)

PUMP	OK	TYPE OF OUTRIGGER	—
MAIN WINCH	—	OUTRIGGER CYLINDER	—
AUX WINCH	—	OUTRIGGER EXTENSION	—
BOOM EXTENSION	OK	SWING	OK
BOOM HOIST	NOT FULLOPERATION TEST / フルオペレーションテスト未実施	CONTROL LEVER	OK
NOTE	NOT PERFORMED DUE TO SEVERE OIL LEAKAGE. / オイル漏れ激しいためフルオペレーションテスト未実施		

ELECTRICAL

LIGHT	—
WIPER	—
HEATER	—
A/C	—
BATTERY	OK
NOTE	

HOOK

CAPACITY	MAIN	— (t)	SUB	— (t)	
NO. OF HOOK	— pcs				
WIRE LOUPE	—				
NOTE					

BOOM

LENGTH	21 m
CONDITION	OK
SHEEVE	—
NOTE	

FORK LIFT

TYPE	—		
FORK	LENGTH	— mm	
	—		
MAST	LENGTH	— mm	
	—		
HYDRAULIC: LIFT CYLINDER	—		
HYDRAULIC: TILT CYLINDER	—		
HYDRAULIC: HOIST CYLINDER	—		
NOTE			

UNDERCARRIAGE

TIRE: SIZE	—	
TIRE: CONDITION	–	
SHOE: ☑ W/PAD 500 mm	TYPE	STEEL
	OK	
PIN BUSH	OK	
CARRIER ROLLER	OK	
TRACK ROLLER	OK	
FRONT IDLER	OK	
SPROCKET	OK	
NOTE		

TRANSMISSION

NO. OF SPEED	F	—	R	—
SHIFT	—			
OIL	—			
NOTE				

JIB

NO. OF SEC	— sec
CONDITON	—
NOTE	

SAFTY DEVICE

MONITOR	–
AML	—
OVER WIND CUT	—
NOTE	

BRAKE

FOOT	–
PARKING	–
NOTE	

CAB	—
SEAT	—
NOTE	

REMARK

OIL LEAKING SEVERELY FROM PIPING DURING BOOM SWINGING AND UP. / ブーム旋回中および上昇中配管よりオイル漏れ大
☐

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました