



GREEN AUCTION

| | | | |
|-------|---------|----------|------------|
| LotNo | 2252004 | LOCATION | YOKOHAMA-E |
|-------|---------|----------|------------|

EXCAVATOR

152th Tender Auction 2025/06/26 ~ 2025/06/27

| | | | |
|-------|-------------|-------|------|
| MAKER | CATERPILLAR | YEAR | 2014 |
| MODEL | 308ESR | HOURL | 4657 |
| S/N | JSN00388 | | |

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

| | | |
|--------|---------|-----------------|
| ENGINE | MODEL | V3307 |
| | S/N | V3307-T-8EC2558 |
| | COOLANT | OK |
| | OIL | OK |
| | START | OK |
| | BLOW-BY | NO/なし |
| | NOISE | NO/なし |
| | EPA | NO/なし |
| | NOTE | |
| | | |

| | | | |
|---------------|--------------------------------|------|-------|
| UNDERCARRIAGE | SHOE | TYPE | STEEL |
| | <input type="checkbox"/> W/PAD | OK | |
| | 450 mm | | |
| | PIN BUSH | OK | |
| | CARRIER ROLLER | OK | |
| | TRACK ROLLER | OK | |
| | FRONT IDLER | OK | |
| | SPROCKET | OK | |
| | NOTE | | |
| | | | |

| | | | |
|------------------|--------|--------|---------|
| FRONT ATTACHMENT | BOOM | TYPE | OFF-SET |
| | | OK | |
| | ARM | TYPE | STD |
| | | OK | |
| | PIPING | - | |
| | BUCKET | TYPE | STD |
| | | OK | |
| | BLADE | OK | |
| | PINS | BOOM | OK |
| | | ARM | OK |
| | | BUCKET | OK |
| | NOTE | | |

| | | |
|---------|---------------|---------------------|
| CAB/CNP | CAB/CNP | OK |
| | ROPS | NO/なし |
| | SEAT | OK |
| | CONTROL LEVER | OK |
| | A/C OR HEATER | OK ONLY BLOWER/送風のみ |
| | COMPUTER | OK |
| | MONITOR | OK |
| | BATTERY | OK |
| | NOTE | |
| | | |

| | | |
|-----------|--------|----|
| CYLINDERS | BOOM | OK |
| | SWING | OK |
| | ARM | OK |
| | BUCKET | OK |
| | BLADE | OK |
| | NOTE | |

| | |
|------------|----|
| TURN TABLE | OK |
|------------|----|

| | | |
|---------|----------------|----|
| CONTROL | HYDRAULIC PUMP | OK |
| | TRAVEL | OK |
| | SWING | OK |
| | CONTROL | OK |
| | NOTE | |

| | |
|------------|---|
| ATTACHMENT | - |
|------------|---|

REMARK

1.7t CRANE HOOK, 4 WAY MULTI LEVER

STARTER WORKING IS NOT VERY GOOD AT TIMES. セルモーター飛び込み悪いときがある RELEASING CHARGE JPY10000 在庫料 ¥10,000

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました