



GREEN AUCTION

LOADER

138th Internet Auction 2026/03/12 ~ 2026/03/13

| | | | |
|-------|----------------------|----------|-----------|
| LotNo | 3138007 | LOCATION | HAKATA-A* |
| MAKER | HITACHI | YEAR | 1995 |
| MODEL | LX70SS-2C | HOUR | 5851 |
| S/N | 41S-02587 (L70-2587) | MILE | 6790km |

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

| | | |
|--------|--|--------------------|
| ENGINE | MODEL | - |
| | S/N | - |
| | COOLANT | OK |
| | OIL | NOT ENOUGH/少ない |
| | START | OK |
| | BLOW-BY | YES/あり(SLIGHTLY/小) |
| | NOISE | NO/なし |
| | EPA | NO/なし |
| NOTE | INJECTION PUMP, TAPPET COVER OIL LEAKING. 噴射ポンプ タペットカバー付近油漏れあり | |

| | | |
|--------------|---------|------------|
| CABIN/CANOPY | CAB/CNP | CRACKED/割れ |
| | ROPS | NO/なし |
| | SEAT | TORN/破れ |
| | NOTE | |

| | | |
|------------|---------|-----------|
| ELECTRICAL | LIGHT | - |
| | WIPER | - |
| | HEATER | - |
| | A/C | - |
| | BATTERY | DEFECT/不良 |
| | NOTE | |

| | | |
|-----------|-------------------|---|
| HYDRAULIC | PUMP | - |
| | LIFT CYLINDER | MINOR OIL LEAK / 油にじみ (LEFT) |
| | TILT CYLINDER | - |
| | STEERING CYLINDER | OIL LEAKING / 油漏れ |
| | LINE | - |
| | NOTE | UNDER COVER OIL LEAKING SEVERELY. アンダーカバーより作動油漏れ大 |

| | | | |
|--------------|-------|---|--|
| TRANSMISSION | GEAR | OK | |
| | SHIFT | OK | |
| | OIL | OK | |
| | NOTE | UNDER CARRIAGE MINOR OIL LEAKING. 足回り全体的に油にじみ | |

| | | |
|-------|------------|----------|
| FRAME | MAIN FRAME | RUSTY/サビ |
| | CENTER PIN | OK |
| | NOTE | |

| | | |
|-------|-----------|---------|
| TIRES | SIZE | 16.9-24 |
| | CONDITION | OK |
| | NOTE | |

| | | |
|------------------|--------------------|----|
| BRAKE & STEERING | FOOT BRAKE | OK |
| | PARKING BRAKE | OK |
| | STEERING OPERATION | OK |
| | NOTE | |

| | |
|----------------|-----------------------|
| DIFF.CASE(F) | MINOR OIL LEAK / 油にじみ |
| DIFF.CASE(R) | MINOR OIL LEAK / 油にじみ |
| COUNTER WEIGHT | OK |

| | | |
|--------|-------------------|-----|
| ARM | ARM | OK |
| | PINS | OK |
| BUCKET | TYPE | STD |
| | SERIAL | - |
| | EDGE | OK |
| | TEETH | - |
| | GENERAL CONDITION | - |
| NOTE | | |

| |
|-------|
| BLANK |
|-------|

| | |
|--------|---|
| REMARK | ENGINE OIL LEAKING. NEED CURING. エンジン始動油漏れ 養生必要 |
|--------|---|

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました