



| | | | |
|-------|------------|----------|-------------|
| LotNo | 1140010 | LOCATION | YOKOHAMA-E* |
| MAKER | KOBELCO | YEAR | 2015 |
| MODEL | SK20UR-2 | HOOR | 2854 |
| S/N | PB04-01117 | | |

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不動車

| | | | |
|--------|---------|---------|--|
| ENGINE | MODEL | L3E-E3 | |
| | S/N | 245746 | |
| | COOLANT | OK | |
| | OIL | OK | |
| | START | OK | |
| | BLOW-BY | NO / なし | |
| | NOISE | NO / なし | |
| | EPA | NO / なし | |
| | NOTE | | |

| | | | |
|------------------|--------|------|---------|
| FRONT ATTACHMENT | BOOM | TYPE | OFF-SET |
| | | OK | |
| | ARM | TYPE | STD |
| | | OK | |
| | PIPING | - | |
| | BUCKET | TYPE | STD |
| | | OK | |
| | BLADE | OK | |
| | PINS | BOOM | OK |
| | | ARM | OK |
| BUCKET | | OK | |
| NOTE | | | |

| | | |
|-----------|--------|----|
| CYLINDERS | BOOM | OK |
| | SWING | - |
| | ARM | OK |
| | BUCKET | OK |
| | BLADE | OK |
| | NOTE | |

| | |
|------------|----|
| TURN TABLE | OK |
|------------|----|

| | | |
|---------|--------------------|----|
| CONTROL | HYDRAULIC PUMP | OK |
| | TRAVEL | OK |
| | SWING | - |
| | CONTROL | OK |
| NOTE | 4WAY MULTI/4WAYマルチ | |

| | |
|------------|---|
| ATTACHMENT | - |
|------------|---|

REMARK

*PUNCHED NO. PARTIALLY UNCLEAR (刻印一部不鮮明)

NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP / 在来船輸出の場合は要洗車

| | | | |
|---------------|---|------|--------|
| UNDERCARRIAGE | SHOE | TYPE | RUBBER |
| | <input checked="" type="checkbox"/> W/PAD | | |
| | 250 mm | | |
| | PIN BUSH | - | |
| | CARRIER ROLLER | - | |
| | TRACK ROLLER | OK | |
| | FRONT IDLER | OK | |
| | SPROCKET | OK | |
| | NOTE | | |

| | | |
|---------|---------------|---------|
| CAB/CNP | CAB/CNP | OK |
| | ROPS | NO / なし |
| | SEAT | OK |
| | CONTROL LEVER | OK |
| | A/C OR HEATER | - |
| | COMPUTER | OK |
| | MONITOR | - |
| | BATTERY | OK |
| | NOTE | |

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました