



GREEN AUCTION

MINI EXCAVATOR

LotNo	1143015	LOCATION	HAKATA-A*
MAKER	IHI	YEAR	-
MODEL	IS-30FX	HOURL	297
S/N	10111874		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	-
	S/N	-
	COOLANT	SIGNS OVERHEAT. / オーバーヒート気味
	OIL	OK
	START	OK
	BLOW-BY	YES / あり(SLIGHTLY/小)
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	OVERALL MINOR OIL LEAK. / 全体的にオイルにじみ

UNDERCARRIAGE	SHOE ☐ W/PAD	TYPE	STEEL
	300 mm	LOOSE / ガタ	RUSTY / サビ
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	LOOSE / ガタ	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	SLOPE
		OK	
	BLADE	LEVER STUCK SIGNS / レバー固着気味	
	PINS	BOOM	LOOSE / ガタ (SEVERELY/大)
		ARM	LOOSE / ガタ (SEVERELY/大)
		BUCKET	LOOSE / ガタ (SEVERELY/大)
NOTE			

CAB/CNP	CAB/CNP	BROKEN / 破損
	ROPS	NO / なし
	SEAT	TORN / 破れ
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	-
	MONITOR	-
	BATTERY	OK
	NOTE	

CYLINDERS	BOOM	MINOR OIL LEAK. / オイルにじみ
	SWING	OK
	ARM	MINOR OIL LEAK. / オイルにじみ
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	LOOSE / ガタ
------------	------------

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK
SIGNS OVERHEAT. / オーバーヒート気味 HOUR METER DEFECT. / アワーメーター不良
NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP / 在来船輸出の場合は要洗車

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました