LotNo 2134004 LOCATION HAKATA-A	
MODEL B7-3 HOUR 8884 □ DOCUMENT/書類 □ UNABLE TO TRAVE	L(START)/不動車
DOCUMENT/書類 □ UNABLE TO TRAVE	
	レ漏れ小
MODEL 4TNV98EBX BOOM TYPE OFF-SET BOOM OIL LEAKING SLIGHTLY/オイル	
S/N 07849 OK SWING OK	
COOLANT OK ARM TYPE STD C. ARM OK	
OIL OK OIL OK START OK PIPING - PIPING - PIPING - BLADE OK BLADE OK	
START OK PIPING - BUCKET TYPE STD BUCKET TYPE STD	
Z I BUCKET LIPE 21D	
BLOW-BY NO/tal BLOW-BY NO/tal OK OK OK OK OK OK OK OK OK O	
NOISE NO/なし DK BLADE OK	
BLOW-BY NO/\$L NO/\$L NO/\$L DK NO/\$L BLADE OK DINS BOOM OK TURN TABLE OK TURN TABLE OK TURN TABLE OK DK DK DK DK DK DK DK	
NOTE ARM OK	
BUCKET LOOSE/ガタ(SLIGHTLY/小) HYDRAULIC PUMP OK	
NOTE TRAVEL OK	
S SWING OK	
SHOE TYPE STEEL W/PAD OK CAB/CNP OK CAB/CNP OK CAB/CNP OK	
OK O	
PIN BUSH OK SEAT OK	
CARRIER ROLLER OK CONTROL OK	
RACK ROLLER OK A/C OR DEFECT/不良 ATTACHMENT -	
ROLLER DEFECT/不良 FRONT OK	
CARRIER ROLLER OK TRACK ROLLER OK FRONT IDLER SPROCKET OK CONTROL LEVER A/C OR DEFECT/不良 COMPUTER OK MONITOR OK MONITOR OK NEED WASHING FOR SHIPPING ON BULK	
SPROCKET OK MONITOR OK NEED WASHING FOR SHIPPING ON BULK 船輸出の場合は要洗車	CARRIER SHIP. 在来

ATTENTION/注意

- *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました

NOTE