



LotNo	4138001	LOCATION	YOKOHAMA-E
MAKER	FURUKAWA	YEAR	1985
MODEL	CD5PB	HOUR (ON DASHBOARD)	1770
S/N	611-6572	HOUR (ON ENGINE)	

DOCUMENT/書類  UNABLE TO TRAVEL(START)/不自動車

ENGINE	MODEL	S4E
	S/N	052333
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO/なし
	NOISE	NO/なし
	EPA	NO/なし
NOTE	MINOR OIL LEAKING. 油にじみ	

TRANSMISSION	OK
MAIN CLUTCH	OK
STEERING CLUTCH	OK
BRAKE	OK
NOTE	

MAIN FRAME	OK
TRACK ROLLER FRAME	OK
NOTE	

CABIN/CANOPY	CAB/CNP	OK
	ROPS	NO/なし
	SEAT	-
	BATTERY	DEAD/あがり
	NOTE	ARM REST BROKEN. 肘掛破損

	TYPE	ANGLE
FRONT ATTACHMENT		OK
	TYPE	-
REAR ATTACHMENT		-
NOTE	BLADE LOWER RIGHT TURNED UP. プレード右下めくれあり	

UNDERDRRAGE	LEFT		RIGHT		
	SHOE	TYPE	LGP	WIDTH	500 mm
	<input type="checkbox"/> W/PAD	OK		OK	
	PIN BUSH	OK		OK	
	CARRIER ROLLER	OK		OK	
	IDLER	OK		OK	
	TRACK ROLLER	OK		OK	
	SPROCKET	OK		OK	
NOTE	RIGHT SHOE BROKEN PARTIALLY. BOLT MUD STUCK SLIGHTLY. ATTENTION, NEED WASHING. 右シュー一部破損あり ボルト付近泥付着小洗車注意				

CYLINDERS	LIFT	OK
	TILT	MINOR OIL LEAK / 油にじみ
	ANGLE	OK
	NOTE	

BLANK
REMARK
HYDRAULIC TANK DENT. BOTH SIDES ENGINE COVER MISSING. BODY PUNCHED S/N UNKNOWN. 作動油タンクへこみ エンジンカバー左右とも欠品 刻印不明不明

ATTENTION/注意

\*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました