



|       |            |          |        |
|-------|------------|----------|--------|
| LotNo | 6139002    | LOCATION | KOBE-N |
| MAKER | MITSUBISHI | YEAR     | 1998   |
| MODEL | MG230E     | HOUR     | 345    |
| S/N   | 2GB00063   | MILE     | 966KM  |

DOCUMENT/書類     UNABLE TO TRAVEL(START)/不働車

|        |         |             |
|--------|---------|-------------|
| ENGINE | MODEL   | 6D34-TE1    |
|        | S/N     | 6D34-067742 |
|        | COOLANT | OK          |
|        | OIL     | OK          |
|        | START   | OK          |
|        | BLOW-BY | NO / なし     |
|        | NOISE   | NO / なし     |
| EPA    | NO / なし |             |
| NOTE   |         |             |

|              |       |    |
|--------------|-------|----|
| TRANSMISSION | GEAR  | OK |
|              | SHIFT | OK |
|              | OIL   | OK |
|              | NOTE  |    |

|               |   |                         |
|---------------|---|-------------------------|
| HYDRAULIC     | PUMP  | OK                      |
|               | LINE  | OK                      |
|               | LIFT CYLINDER   | OK                      |
|               | TILT CYLINDER   | OK                      |
|               | SIDE SHIFT  | MINOR OIL LEAK / オイルにじみ |
|               | CENTER SHIFT  | OK                      |
|               | ARTICURATOR   | OK                      |
|               | LEANING   | OK                      |
|               | CIRCLE DRIVE  | OK                      |
|               | LINKAGE   | OK                      |
| CONTROL VALVE | OK  |                         |
| OIL LEVEL     | OK  |                         |
| NOTE          | STEERLING CYLINDER MINOR OIL LEAK / ステアリングシリンダーオイルにじみ |                         |

|       |             |                  |
|-------|-------------|------------------|
| FRAME | FRONT FRAME | OK               |
|       | REAR FRAME  | OK               |
|       | CIRCLE GEAR | OK               |
|       | PINION GEAR | OIL LEAK / オイル漏れ |
|       | NOTE        |                  |

|              |         |           |
|--------------|---------|-----------|
| CABIN/CANOPY | CAB/CNP | TORN / 破れ |
|              | ROPS    | NO / なし   |
|              | SEAT    | OK        |
|              | NOTE    |           |

|            |    |
|------------|----|
| FRONT AXLE | OK |
| REAR AXLE  | OK |
| CENTER PIN | OK |
| NOTE       |    |

|            |                     |    |
|------------|---------------------|----|
| ATTACHMENT | BLADE               | OK |
|            | RIPPER OR SCARIFIER | OK |
|            | NOTE                |    |

|       |         |                  |
|-------|---------|------------------|
| BRAKE | FOOT    | OIL LEAK / オイル漏れ |
|       | PARKING | OK               |
|       | NOTE    |                  |

|       |                |               |
|-------|----------------|---------------|
| TIRES | SIZE           | 11.00-20 10PR |
|       | TIRE CONDITION | OK            |
|       | NOTE           |               |

|            |         |                                     |
|------------|---------|-------------------------------------|
| ELECTRICAL | LIGHT   | OK                                  |
|            | WIPER   | -                                   |
|            | HEATER  | -                                   |
|            | A/C     | -                                   |
|            | BATTERY | OK                                  |
|            | NOTE    | BATTERY CHARGE IS OK (CHARGING 28V) |

REMARK

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました