



LotNo	2139001	LOCATION	HAKATA-S*
MAKER	KOBELCO	YEAR	1996
MODEL	SK60	HOURL	9375
S/N	LE-20577		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	-	
	S/N	-	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO / なし	
	NOISE	NO / なし	
	EPA	NO / なし	
	NOTE	OIL LEAK / オイル漏れ WATER LEAK/水漏れ ENGINE MOUNT BREAKAGE/エンジンマウント折損 LEFT PILOT BULB DEFECT / 左パイロットバルブ不良	

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	SLOPE
		OK	
	BLADE	-	
	PINS	BOOM	OK
		ARM	OK
BUCKET		OK	
NOTE			

CYLINDERS	BOOM	RUSTY / サビ
	SWING	-
	ARM	MINOR OIL LEAK / オイルにじみ
	BUCKET	OIL LEAK / オイル漏れ
	BLADE	-
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
NOTE		

ATTACHMENT	-
------------	---

REMARK

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD	OK	
	<input type="text"/> mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	SPEED-REDUCTION MINOR OIL LEAK / 走行減速機カバーよりオイルにじみ SOILED, CAUTION, NEED WASHING. / よごれ、洗車注意	

CAB/CNP	CAB/CNP	DOOR CRACK / 亀裂	
	ROPS	NO / なし	
	SEAT	OK	
	CONTROL LEVER	OK	
	A/C OR HEATER	-	
	COMPUTER	OK	
	MONITOR	OK	
	BATTERY	OK	
	NOTE	GAS CYLINDER DEFECT / ガスシリンダー不良 ROCK LEVER MISSING/ロックレバー欠損 DOOR GLASS FRONT UNDER GLASS PLASTIC/ドアガラス・フロントロウガラスがプラスチック板	

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました