



LotNo	1260014	LOCATION	YOKOHAMA-E
MAKER	KUBOTA	YEAR	2014
MODEL	RX-306	HOOR	4555
S/N	15664		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	D1703
	S/N	7EW9339
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	-
	NOTE	

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
		MINOR OIL LEAK/油にじみ	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
BUCKET		OK	
NOTE	ARM CRANE/アームクレーン		

CYLINDERS	BOOM	OK
	SWING	-
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	-
	CONTROL	OK
NOTE	3WAY MULTI LEVER/3WAYマルチレバー MINOR OIL LEAKING FROM CONTROL VALVE/コントロールバルブから油にじみ	

ATTACHMENT	-
------------	---

REMARK	OIL LEAKING FROM BOTTOM OF THE UNIT./本体下部から油漏れ SERIAL PLATE MISSING / シリアルプレート紛失
--------	---

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD	OK	
	300 mm		
	PIN BUSH	-	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました