



|       |         |          |        |
|-------|---------|----------|--------|
| LotNo | 1142003 | LOCATION | KOBE-N |
| MAKER | HITACHI | YEAR     | 2006   |
| MODEL | ZX20UR  | HOOR     | 549    |
| S/N   | 10001   |          |        |

DOCUMENT/書類     UNABLE TO TRAVEL(START)/不働車

|        |         |                  |
|--------|---------|------------------|
| ENGINE | MODEL   | —                |
|        | S/N     | —                |
|        | COOLANT | OK               |
|        | OIL     | OK               |
|        | START   | OK               |
|        | BLOW-BY | NO / なし          |
|        | NOISE   | NO / なし          |
|        | EPA     | YES / あり         |
|        | NOTE    | OIL LEAK / オイル漏れ |

|                  |        |      |         |
|------------------|--------|------|---------|
| FRONT ATTACHMENT | BOOM   | TYPE | OFF-SET |
|                  |        |      | OK      |
|                  | ARM    | TYPE | STD     |
|                  |        |      | OK      |
|                  | PIPING |      | —       |
|                  | BUCKET | TYPE | SLOPE   |
|                  |        |      | OK      |
|                  | BLADE  |      | OK      |
|                  | PINS   | BOOM | OK      |
|                  |        | ARM  | OK      |
|                  | BUCKET | OK   |         |
| NOTE             |        |      |         |

|           |        |    |
|-----------|--------|----|
| CYLINDERS | BOOM   | OK |
|           | SWING  | OK |
|           | ARM    | OK |
|           | BUCKET | OK |
|           | BLADE  | OK |
|           | NOTE   |    |

|            |    |
|------------|----|
| TURN TABLE | OK |
|------------|----|

|         |                |    |
|---------|----------------|----|
| CONTROL | HYDRAULIC PUMP | OK |
|         | TRAVEL         | OK |
|         | SWING          | OK |
|         | CONTROL        | OK |
| NOTE    |                |    |

|            |   |
|------------|---|
| ATTACHMENT | — |
|------------|---|

REMARK

|               |                                |      |        |
|---------------|--------------------------------|------|--------|
| UNDERCARRIAGE | SHOE                           | TYPE | RUBBER |
|               | <input type="checkbox"/> W/PAD |      |        |
|               | 250 mm                         | OK   |        |
|               | PIN BUSH                       | OK   |        |
|               | CARRIER ROLLER                 | —    |        |
|               | TRACK ROLLER                   | OK   |        |
|               | FRONT IDLER                    | OK   |        |
|               | SPROCKET                       | OK   |        |
| NOTE          |                                |      |        |

|         |               |                                       |
|---------|---------------|---------------------------------------|
| CAB/CNP | CAB/CNP       | DAMAGED / 損傷                          |
|         | ROPS          | NO / なし                               |
|         | SEAT          | DEFECT / 破れ                           |
|         | CONTROL LEVER | OK                                    |
|         | A/C OR HEATER | —                                     |
|         | COMPUTER      | —                                     |
|         | MONITOR       | —                                     |
|         | BATTERY       | OK                                    |
|         | NOTE          | BOOM CONTACTS CANOPY / ブームとキャノピーが干渉する |

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました