



LotNo	1142008	LOCATION	KOBE-N
MAKER	KOMATSU	YEAR	1994
MODEL	PC28UU-2	HOOR	5820
S/N	10116		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	—
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	ENGINE BOTTOM WET WITH OIL

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
		WELD REPAIR & CRACK / 溶接、割れ	
	ARM	TYPE	STD
		OK	
	PIPING	—	
	BUCKET	TYPE	W/STD BKT
		—	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
	BUCKET	OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
NOTE		

ATTACHMENT	GRAPPRE
------------	---------

REMARK

MECHANICAL GRAPPLE. WITH BUCKET AND LINKS. / グラップル装着。バケット&リンク付属

NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP / 在来船輸出の場合は要洗車

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD	OK	
	300 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	DEFECT / 破れ
	CONTROL LEVER	OK
	A/C OR HEATER	—
	COMPUTER	—
	MONITOR	—
	BATTERY	OK
	NOTE	

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました