



LotNo	1142015	LOCATION	YOKOHAMA-E
MAKER	KUBOTA	YEAR	2015
MODEL	U-30-6	HOURL	4166
S/N	10159		

DOCUMENT/書類     UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	V1703
	S/N	7FK4483
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	

FRONT ATTACHMENT	BOOM	TYPE	SWING
			OK
	ARM	TYPE	STD
			OK
	PIPING		OK
	BUCKET	TYPE	STD
			OK
	BLADE		OK
	PINS	BOOM	LOOSE / ガタ (SLIGHTLY/小)
		ARM	OK
	BUCKET	OK	
NOTE			

CYLINDERS	BOOM	OIL LEAKING SLIGHTLY / オイル漏れ小
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
NOTE		

ATTACHMENT	-
------------	---

REMARK

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD		
	300 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
NOTE			

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	CRACK / 亀裂
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました