



GREEN AUCTION

## EXCAVATOR

|       |             |          |          |
|-------|-------------|----------|----------|
| LotNo | 2263005     | LOCATION | HAKATA-A |
| MAKER | CATERPILLAR | YEAR     | 2013     |
| MODEL | 311DRR      | HOUR     | 5966     |
| S/N   | AKW01578    |          |          |

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

|        |         |                  |
|--------|---------|------------------|
| ENGINE | MODEL   | C4.2             |
|        | S/N     | JKH21037         |
|        | COOLANT | OK               |
|        | OIL     | OK               |
|        | START   | NOT TESTED / 未確認 |
|        | BLOW-BY | NOT TESTED / 未確認 |
|        | NOISE   | NOT TESTED / 未確認 |
|        | EPA     | NO / なし          |
|        | NOTE    |                  |

|               |                                           |                                                                            |       |
|---------------|-------------------------------------------|----------------------------------------------------------------------------|-------|
| UNDERCARRIAGE | SHOE                                      | TYPE                                                                       | STEEL |
|               | <input checked="" type="checkbox"/> W/PAD |                                                                            |       |
|               | 500 mm                                    | OK                                                                         |       |
|               | PIN BUSH                                  | OK                                                                         |       |
|               | CARRIER ROLLER                            | OK                                                                         |       |
|               | TRACK ROLLER                              | OK                                                                         |       |
|               | FRONT IDLER                               | OK                                                                         |       |
|               | SPROCKET                                  | OK                                                                         |       |
|               | NOTE                                      | DUE TO CORROSION MOTOR HOSE OIL LEAKING SEVERELY. / 走行モーターホースの腐食によりオイル漏れ大口 |       |

|                  |        |        |     |
|------------------|--------|--------|-----|
| FRONT ATTACHMENT | BOOM   | TYPE   | STD |
|                  |        |        | OK  |
|                  | ARM    | TYPE   | STD |
|                  |        |        | OK  |
|                  | PIPING |        | -   |
|                  | BUCKET | TYPE   | STD |
|                  |        |        | OK  |
|                  | BLADE  |        | -   |
|                  | PINS   | BOOM   | OK  |
|                  |        | ARM    | OK  |
|                  |        | BUCKET | OK  |
|                  | NOTE   |        |     |

|         |               |           |
|---------|---------------|-----------|
| CAB/CNP | CAB/CNP       | OK        |
|         | ROPS          | NO / なし   |
|         | SEAT          | TORN / 破れ |
|         | CONTROL LEVER | OK        |
|         | A/C OR HEATER | OK        |
|         | COMPUTER      | OK        |
|         | MONITOR       | OK        |
|         | BATTERY       | OK        |
|         | NOTE          |           |

|           |        |    |
|-----------|--------|----|
| CYLINDERS | BOOM   | OK |
|           | SWING  | -  |
|           | ARM    | OK |
|           | BUCKET | OK |
|           | BLADE  | -  |
|           | NOTE   |    |

|            |    |
|------------|----|
| TURN TABLE | OK |
|------------|----|

|         |                |    |
|---------|----------------|----|
| CONTROL | HYDRAULIC PUMP | OK |
|         | TRAVEL         | -  |
|         | SWING          | -  |
|         | CONTROL        | -  |
|         | NOTE           |    |

|            |   |
|------------|---|
| ATTACHMENT | - |
|------------|---|

|                                                                                          |
|------------------------------------------------------------------------------------------|
| REMARK                                                                                   |
| NEED WASHING. / 要洗車<br>*NEED REPAIR 要修理                                                  |
| ENGINE OPERATION TEST NOT PERFORMED DUE TO SEVERE OIL LEAKAGE. / オイル漏れ激しいため、エンジン稼働テスト未実施 |

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
\*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
\*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました