



GREEN AUCTION

MINI EXCAVATOR

| | | | |
|-------|----------|----------|--------|
| LotNo | 1129011 | LOCATION | KOBE-N |
| MAKER | KOMATSU | YEAR | 2004 |
| MODEL | PC30MR-2 | HOOR | 2798 |
| S/N | 21486 | | |

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

| | | |
|--------|---------|------------|
| ENGINE | MODEL | — |
| | S/N | — |
| | COOLANT | RUSTY / サビ |
| | OIL | OK |
| | START | OK |
| | BLOW-BY | NO / なし |
| | NOISE | NO / なし |
| | EPA | YES / あり |
| | NOTE | |

| | | | |
|---------------|---|-----------------------------|-------|
| UNDERCARRIAGE | SHOE | TYPE | STEEL |
| | <input checked="" type="checkbox"/> W/PAD | | |
| | 300 mm | MANY PADS MISSING / パッド欠損多い | |
| | PIN BUSH | OK | |
| | CARRIER ROLLER | OK | |
| | TRACK ROLLER | OK | |
| | FRONT IDLER | OK | |
| | SPROCKET | OK | |
| | NOTE | | |

| | | | |
|------------------|--------|--|-------------------------|
| FRONT ATTACHMENT | BOOM | TYPE | SWING |
| | | OK | |
| | ARM | TYPE | STD |
| | | OK | |
| | PIPING | HOSE NEEDS REPAIRE (BURST) / ホース破れ修理必要 | |
| | BUCKET | TYPE | STD |
| | | OK | |
| | BLADE | OK | |
| | PINS | BOOM | LOOSE (SLIGHT) / ガタ (小) |
| | | ARM | OK |
| | | BUCKET | OK |
| | NOTE | | |

| | | |
|---------|---------------|-------------|
| CAB/CNP | CAB/CNP | OK |
| | ROPS | YES / あり |
| | SEAT | DEFECT / 不良 |
| | CONTROL LEVER | OK |
| | A/C OR HEATER | — |
| | COMPUTER | — |
| | MONITOR | — |
| | BATTERY | OK |
| | NOTE | |
| | | |
| | | |

| | | |
|-----------|--------|-------------------------|
| CYLINDERS | BOOM | OK |
| | SWING | OK |
| | ARM | OK |
| | BUCKET | OK |
| | BLADE | MINOR OIL LEAK / オイルにじみ |
| | NOTE | |

| | |
|------------|----|
| TURN TABLE | OK |
|------------|----|

| | | |
|---------|----------------|-------------------------------|
| CONTROL | HYDRAULIC PUMP | OK |
| | TRAVEL | OK |
| | SWING | OK |
| | CONTROL | OK |
| | NOTE | 4WAY MULTI LEVER / 4WAYマルチレバー |

| | |
|------------|---|
| ATTACHMENT | — |
|------------|---|

| | |
|--------|--|
| REMARK | |
|--------|--|

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました