



LotNo	1259009	LOCATION	OSAKA-S
MAKER	KUBOTA	YEAR	2015
MODEL	RX-306	HOURL	5129
S/N	15835		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	D1703
	S/N	7EY9444
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
			OK
	ARM	TYPE	STD
			OK
	PIPING		-
	BUCKET	TYPE	STD
			OK
	BLADE		OK
	PINS	BOOM	OK
		ARM	OK
	BUCKET	OK	
NOTE			

CYLINDERS	BOOM	OIL LEAK / オイル漏れ (SLIGHT / 小)
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
NOTE	HYDRAULIC OIL MINOR LEAK FROM TRUCK FRAME COVERS / トラックフレームカバーからの軽微なオイル漏れ	

ATTACHMENT	-
------------	---

REMARK	4WAY MULTI LEVER / 4WAYマルチレバー 0.9TON ARM CRANE / クレーン付き
--------	--

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD		
	<input checked="" type="checkbox"/> 300 mm		OK
	PIN BUSH		OK
	CARRIER ROLLER		OK
	TRACK ROLLER		OK
	FRONT IDLER		OK
	SPROCKET		OK
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました