



|       |             |          |        |
|-------|-------------|----------|--------|
| LotNo | 2140008     | LOCATION | KOBE-N |
| MAKER | CATERPILLAR | YEAR     | 2009   |
| MODEL | 313DCR      | HOUR     | 5578   |
| S/N   | LCE00222    |          |        |

DOCUMENT/書類     UNABLE TO TRAVEL(START)/不働車

|        |         |          |
|--------|---------|----------|
| ENGINE | MODEL   | C4.2     |
|        | S/N     | JKH03201 |
|        | COOLANT | OK       |
|        | OIL     | OK       |
|        | START   | OK       |
|        | BLOW-BY | NO / なし  |
|        | NOISE   | NO / なし  |
|        | EPA     | YES / あり |
|        | NOTE    |          |

|                  |        |      |     |
|------------------|--------|------|-----|
| FRONT ATTACHMENT | BOOM   | TYPE | STD |
|                  |        |      | OK  |
|                  | ARM    | TYPE | STD |
|                  |        |      | OK  |
|                  | PIPING |      | OK  |
|                  | BUCKET | TYPE | STD |
|                  |        |      | OK  |
|                  | BLADE  |      | -   |
|                  | PINS   | BOOM | OK  |
|                  |        | ARM  | OK  |
|                  | BUCKET | OK   |     |
| NOTE             |        |      |     |

|           |        |    |
|-----------|--------|----|
| CYLINDERS | BOOM   | OK |
|           | SWING  | -  |
|           | ARM    | OK |
|           | BUCKET | OK |
|           | BLADE  | -  |
|           | NOTE   |    |

|            |    |
|------------|----|
| TURN TABLE | OK |
|------------|----|

|         |                               |    |
|---------|-------------------------------|----|
| CONTROL | HYDRAULIC PUMP                | OK |
|         | TRAVEL                        | OK |
|         | SWING                         | OK |
|         | CONTROL                       | OK |
| NOTE    | 4WAY MULTI LEVER / 4WAYマルチレバー |    |

|            |   |
|------------|---|
| ATTACHMENT | - |
|------------|---|

REMARK

\*PUNCHED NO. UNCLEAR (刻印不鮮明)

|               |                                           |                                               |       |
|---------------|-------------------------------------------|-----------------------------------------------|-------|
| UNDERCARRIAGE | SHOE                                      | TYPE                                          | STEEL |
|               | <input checked="" type="checkbox"/> W/PAD |                                               |       |
|               | 500 mm                                    | OK                                            |       |
|               | PIN BUSH                                  | OK                                            |       |
|               | CARRIER ROLLER                            | OK                                            |       |
|               | TRACK ROLLER                              | OK                                            |       |
|               | FRONT IDLER                               | OK                                            |       |
|               | SPROCKET                                  | OK                                            |       |
|               | NOTE                                      | MUD SOILED, CAUTION, NEED WASHING. / 泥汚れ 洗車注意 |       |

|         |               |         |
|---------|---------------|---------|
| CAB/CNP | CAB/CNP       | OK      |
|         | ROPS          | NO / なし |
|         | SEAT          | OK      |
|         | CONTROL LEVER | OK      |
|         | A/C OR HEATER | OK      |
|         | COMPUTER      | -       |
|         | MONITOR       | -       |
|         | BATTERY       | OK      |
|         | NOTE          |         |

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました