



LotNo	2141005	LOCATION	KOBE-N
MAKER	CATERPILLAR	YEAR	—
MODEL	308E2CR	HOOR	1024
S/N	MY201929		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	C3.3B
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	YES / あり
	NOTE	CHARGING FAILURE / 充電不良

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING		OK
	BUCKET	TYPE	STD
			OK
	BLADE		OK
	PINS	BOOM	OK
		ARM	OK
	BUCKET	OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	—
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
NOTE	4WAY MULTI LEVER / 4WAYマルチレバー	

ATTACHMENT	—
------------	---

REMARK
 ENGINE STALLS WHEN JUMP BATTERY IS DISCONNECTED. / ジャンプバッテリー外すとエンジン停止する
 BATTERY REPLACEMENT OR ALTERNATOR REPAIR REQUIRED BEFORE SHIPPING. / 出庫の際はバッテリー交換か、もしくはオルタネーターの修理が必要
 *NEED LIFT CHARGE FOR RELEASING (別途リフトチャージ必要)

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD		
	450 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	DEAD / あがり
	NOTE	

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました