



## GREEN AUCTION

LotNo	2252007	LOCATION	HAKATA-A
-------	---------	----------	----------

## EXCAVATOR

152th Tender Auction 2025/06/26 ~ 2025/06/27

MAKER	KOMATSU	YEAR	1993
MODEL	PC120-6	HOUR	10661
S/N	45264		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	S4D95L-1
	S/N	153359
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO/なし
	NOISE	NO/なし
	EPA	NO/なし
	NOTE	

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input type="checkbox"/> W/PAD	OK	
	500 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	-	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	DOOR NOT CLOSE.ドア閉まらない
	ROPS	NO/なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	-
	MONITOR	DEFECT/不良
	BATTERY	DEAD/あがり
	NOTE	CORRODED SEVERELY. 腐食多い

CYLINDERS	BOOM	OK
	SWING	-
	ARM	OK
	BUCKET	OK
	BLADE	-
	NOTE	

TURN TABLE	NG
------------	----

CONTROL	HYDRAULIC PUMP	OIL LEAKING MODERATELY/オイル漏れ中
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

## REMARK

NEED WASHING. OIL LEAKING, NEED REPAIR. 要洗車 オイル漏れ要修理

## ATTENTION/注意

\*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
\*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
\*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged  
\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました