



LotNo	2131012	LOCATION	KOBE-N
MAKER	CATERPILLAR	YEAR	2008
MODEL	320D	HOUR	5527
S/N	BWZ02537		

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	C6.4
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES / あり (SLIGHTLY/小)
	NOISE	NO / なし
	EPA	YES / あり
	NOTE	

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		PATCH, CRACKED / パッチ, 亀裂	
	PIPING	—	
	BUCKET	TYPE	STD
		OK	
	BLADE	—	
	PINS	BOOM	OK
		ARM	OK
BUCKET		OK	
NOTE			

CYLINDERS	BOOM	OIL LEAK, DROP / オイル漏れ, 滴下
	SWING	—
	ARM	OK
	BUCKET	OK
	BLADE	—
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	4WAY MULTI LEVER / 4WAYマルチレバー

ATTACHMENT	—
------------	---

REMARK	2.9T ARM CRANE / クレーン付き
--------	-------------------------

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input type="checkbox"/> W/PAD	CRACKED, BENT, SOME LOST / 割れ,曲がり,一部紛失	
	600 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	STUCK / 固着	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
NOTE	RUSTY / サビ		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	DEFECT / 不良
	COMPUTER	OK
	MONITOR	OK
	BATTERY	DEAD / あがり
	NOTE	

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました