



GREEN AUCTION

MANLIFT

LotNo	8131022	LOCATION	OSAKA-S
-------	---------	----------	---------

MAKER	TADANO	YEAR	2007				
MODEL	AT-270-2 (PA-FK71D)	HOUR	3517	CARRIER HR	—	CARRIER KM	43754
S/N	370686 (FK71D-701903)	CASSIS MODEL	PA-FK71D	CASSIS S/N	FK71D-701903		

☒ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	H-TYPE	ELECTRICAL	LIGHT	OK	
	MODEL	4M50			MAIN WINCH	—	OUTRIGGER CYLINDER	OK		WIPER	OK	
	S/N	—			AUX WINCH	—	OUTRIGGER EXTENSION	OK		HEATER	OK	
	COOLANT	OK			BOOM EXTENSION	OK	SWING	OK		A/C	OK	
	OIL	OK			BOOM HOIST	OK	CONTROL LEVER	OK		BATTERY	OK	
	START	OK			NOTE					NOTE		
	BLOW-BY	NO / なし										
	NOISE	NO / なし										
	NOTE											

HOOK	CAPACITY	MAIN	—	(t)	SUB	—	(t)	BOOM	LENGTH	—	m	FORK LIFT	TYPE	—	HYDRAULIC	TYPE	—
	NO. OF HOOK	—							pcs	CONDITION	OK		FORK	LENGTH		—	mm
	WIRE ROPE	—								SHEEVE	—			LENGTH		—	mm
	NOTE								NOTE								

TRANSMISSION	NO. OF SPEED	F	6	R	1	JIB	NO. OF SEC	—	sec	SAFETY DEVICE	MONITOR	OK
	SHIFT	OK					CONDITON	—	AML		OK	
	OIL	OK					NOTE		OVER WIND CUT		—	
	NOTE	6M/T					NOTE		NOTE			

CAB	OK	BRAKE	FOOT	OK
SEAT	OK		PARKING	OK
NOTE			NOTE	

TIRE	SIZE	225/80R17.5		UNDERCARRIAGE	SHOE	TYPE	—
	CONDITION	OK			<input type="checkbox"/> W/PAD	—	
		—			mm	—	
	PIN BUSH	—			CARRIER ROLLER TRACK ROLLER	—	
	FRONT IDLER	—			SPROCKET	—	
	NOTE				NOTE		

REMARK	
TADANO 27M MANLIFT TRUCK	
EXTRA RECYCLING FEE JPY 11,010 / リサイクル料	

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました