



GREEN AUCTION

MANLIFT

LotNo	8131019	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	MITSUBISHI	YEAR	2005				
MODEL	SS12A (PA-FE73DB)	HOOR	5836	CARRIER HR	—	CARRIER KM	46111
S/N	693234 (FE73DB-520208)	CASSIS MODEL	PA-FE73DB	CASSIS S/N	FE73DB-520208		

☒ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	H-TYPE	ELECTRICAL	LIGHT	OK
	MODEL	4M50			MAIN WINCH	—	OUTRIGGER CYLINDER	OK		WIPER	OK
	S/N	—			AUX WINCH	—	OUTRIGGER EXTENSION	OK		HEATER	OK
	COOLANT	OK			BOOM EXTENSION	OK	SWING	OK		A/C	OK
	OIL	OK			BOOM HOIST	OK	CONTROL LEVER	OK		BATTERY	DEAD / あがり
	START	OK			NOTE			NOTE			
	BLOW-BY	NO / なし									
	NOISE	NO / なし									
	NOTE										

HOOK	CAPACITY	MAIN	—	(t)	SUB	—	(t)	BOOM	LENGTH	—		m	
	NO. OF HOOK	—							pcs	CONDITION	OK		
	WIRE ROPE	—							SHEEVE	—			
	NOTE								NOTE				

TRANSMISSION	NO. OF SPEED	F	5	R	1	JIB	NO. OF SEC	—		sec
	SHIFT	OK					CONDITON	—		
	OIL	OK					NOTE			
	NOTE	5M/T								

CAB	OK	SAFTY DEVICE	MONITOR	—		
	SEAT		OK	AML	—	
	NOTE			OVER WIND CUT	—	
				NOTE		

FORK LIFT	HYDRAULIC	TYPE	—		
		FORK	LENGTH	—	mm
		MAST	LENGTH	—	mm
		NOTE			
BRAKE	HYDRAULIC	LIFT CYLINDER	—		
		TILT CYLINDER	—		
		HOIST CYLINDER	—		
		NOTE			
FOOT	PARKING	NOTE	OK		
			OK		

TIRE	SIZE	205/85R16	
CONDITION	OK		
SHOE	TYPE	—	
☐ W/PAD	—		
☐ mm	—		
PIN BUSH	—		
CARRIER ROLLER	—		
TRACK ROLLER	—		
FRONT IDLER	—		
SPROCKET	—		
NOTE			

REMARK	AICHI 11.9M MANLIFT		
EXTRA RECYCLING FEE JPY8,830 / リサイクル料			

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a “Successful Bid Fee” will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました