



GREEN AUCTION

LotNo	1133027	LOCATION	HAKATA-S
-------	---------	----------	----------

MAKER	KUBOTA	YEAR	2013
MODEL	U40-6	HOUR	12647
S/N	12647		

MINI EXCAVATOR

133th Internet Auction 2025/09/18 ~ 2025/09/19

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	-	
	S/N	-	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	YES/あり(SLIGHTLY/小)	
	NOISE	NO/なし	
	EPA	NO/なし	
	NOTE	ENGINE MINOR OIL LEAKING. エンジンに油にじみあり	

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD		
	400 mm	CRAWLER CUT. クローラー切れ	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	OK	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	LOOSE/ガタ
		ARM	LOOSE/ガタ
		BUCKET	LOOSE/ガタ
	NOTE		

CAB/CNP	CAB/CNP	DENT/へこみ
	ROPS	NO/なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	COVER RUSTY, SCRATCHED, DENT. UNDER COVER MINOR OIL LEAKING. カバー錆 傷 へこみ アンダーカバー油にじみあり

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	ROD SCRATCHED/ロッド傷あり
	BLADE	OK
	NOTE	

TURN TABLE	LOOSE LATERALLY/横ガタ
------------	---------------------

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました