



GREEN AUCTION

LotNo	1134006	LOCATION	YOKOHAMA-E
-------	---------	----------	------------

MAKER	KUBOTA	YEAR	2006
MODEL	U-20-3S	HOURL	3993
S/N	10597		

MINI EXCAVATOR

134th Internet Auction 2025/10/23 ~ 2025/10/24

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	D1005
	S/N	6J6080
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO/なし
	NOISE	NO/なし
	EPA	NO/なし
	NOTE	

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☒ W/PAD	OK	
	250 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	MUD STUCK SLIGHTLY. 泥付着小	

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	LOOSE SEVERELY/ガタ大きい
		ARM	LOOSE SEVERELY/ガタ大きい
		BUCKET	LOOSE SEVERELY/ガタ大きい
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO/なし
	SEAT	BROKEN/破損
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

CYLINDERS	BOOM	OIL LEAKING SLIGHTLY/オイル漏れ小
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

SIDE COVER BROKEN. RATING PLATE MISSING. NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP. サイドカバー破損 本体プレート欠損 在来船輸出の場合は要洗車

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました