



GREEN AUCTION

EXCAVATOR

LotNo	2135003	LOCATION	KOBE-N
MAKER	KOMATSU	YEAR	2009
MODEL	PC78US-8	HOURL	10350
S/N	15701		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不動車

ENGINE	MODEL	—
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	YES / あり
	NOTE	

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☐ W/PAD		
	450 mm	OK	
	PIN BUSH	KINK / キンク	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	SOILED, CAUTION, NEED WASHING. / よごれ、洗車注意	

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING	OK	GRAPPLE
	BUCKET	TYPE	—
			—
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE	WITH FOREST GRAPPLE / 林業用グラップル付き	

CAB/CNP	CAB/CNP	DAMAGED / 損傷あり
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	—
	COMPUTER	—
	MONITOR	—
	BATTERY	DEAD / あがり
	NOTE	DOOR CANNOT CLOSE TIGHTLY / ドアきっちり閉まらない

CYLINDERS	BOOM	OK
	SWING	—
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	WET & DIRTY WITH OIL (UNDER THE CABIN) / 機体下部オイル濡れ

ATTACHMENT	—
------------	---

REMARK	
--------	--

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました