



GREEN AUCTION

MANLIFT

LotNo	8135001	LOCATION	KOBE-N
-------	---------	----------	--------

MAKER	AICHI	YEAR	1991				
MODEL	SP210	HOURL	7727	CARRIER HR	—	CARRIER KM	—
S/N	424318	CASSIS MODEL	—	CASSIS S/N	—		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	—	
	MODEL	—			MAIN WINCH	—	OUTRIGGER CYLINDER	—	
	S/N	—			AUX WINCH	—	OUTRIGGER EXTENSION	—	
	COOLANT	OK	—		BOOM EXTENSION	OK	SWING	OK	
	OIL	OK	—		BOOM HOIST	OK	CONTROL LEVER	OK	
	START	OK	—		NOTE				
	BLOW-BY	NO / なし	—						
	NOISE	NO / なし	—						
	NOTE	FUEL LEAK SEVERELY (PRIMARY FEED PUMP) / 燃料フィードポンプからの滴下 (大) OIL STAIN / 汚れ							
HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)	BOOM	LENGTH	—	m
	NO. OF HOOK	— pcs					CONDITION	OK	
	WIRE ROPE	—					SHEEVE	—	
	NOTE						NOTE		
TRANSMISSION	NO. OF SPEED	F	—	R	—	JIB	NO. OF SEC	—	sec
	SHIFT	—					CONDITON	—	
	OIL	—					NOTE		
	NOTE								
CAB	—	SAFETY DEVICE	MONITOR	—					
	SEAT		—	AML	—				
	NOTE		—	OVER WIND CUT	—				
			NOTE	FOOT PEDAL IS STUCK / フートペダル固着					
FORK LIFT	TYPE	—		HYDRAULIC	LIFT CYLINDER	—			
	FORK	LENGTH	—		mm	TILT CYLINDER	—		
	MAST	LENGTH	—		mm	HOIST CYLINDER	—		
					NOTE				
BRAKE	FOOT	—		REMARK					
	PARKING	OK			RUSTY / サビ HOUR 5207 + 2520Hr HOUR METER UNKNOWN (ADD-ON) / アワーメーター交換につき不明				
	NOTE								
TIRE	SIZE	9.00-20		UNDERCARRIAGE	SHOE	TYPE	—		
	CONDITION	OK			W/PAD	—	PIN BUSH	—	
					CARRIER ROLLER	—	TRACK ROLLER	—	
					FRONT IDLER	—	SPROCKET	—	
					NOTE				

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました