



GREEN AUCTION

LotNo	1138003	LOCATION	YOKOHAMA-E
-------	---------	----------	------------

MINI EXCAVATOR

138th Internet Auction 2026/03/12 ~ 2026/03/13

MAKER	YANMAR	YEAR	2011
MODEL	B2-5	HOUR	3276
S/N	57143B		

 DOCUMENT/書類
 UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	3TNV76-BX	
	S/N	97537	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO/なし	
	NOISE	NO/なし	
	EPA	YES/あり	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
BUCKET		OK	
NOTE			

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD	OK	
	250 mm		
	PIN BUSH	-	
	CARRIER ROLLER	-	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO/なし
	SEAT	FISSURED/亀裂
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

REMARK	NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP. 在来船輸出の場合は要洗車
--------	--

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませうお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました