



# GREEN AUCTION

LotNo	1259012	LOCATION	HAKATA-S
-------	---------	----------	----------

## MINI EXCAVATOR

159th Tender Auction 2026/03/26 ~ 2026/03/27

MAKER	KUBOTA	YEAR	2015
MODEL	RX-306E	HOUR	6013
S/N	20360		

 DOCUMENT/書類
  UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	D1703
	S/N	7FV0335
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES/あり(SLIGHTLY/小)
	NOISE	NO/なし
	EPA	NO/なし
	NOTE	

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
			OK
	ARM	TYPE	STD
			TIP DENT/先端へこみ
	PIPING		-
	BUCKET	TYPE	STD
			SIDE CUTTER MISSING. サイドカッター欠品
	BLADE		OK
	PINS	BOOM	LOOSE/ガタ
		ARM	LOOSE/ガタ
	BUCKET	LOOSE SEVERELY/ガタ大きい	
NOTE	OFF-SET LOOSE. オフセットガタあり		

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	LOOSE LATERALLY/横ガタ
------------	---------------------

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	CONTROL VALVE MINOR OIL LEAKING. コントロールバルブにじみあり

ATTACHMENT	-
------------	---

### REMARK

COVER DENT. NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP. カバー類へこみ 在来船輸出の場合は要洗車

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD	SCRATCHED/キズあり	
	300 mm		
	PIN BUSH	-	
	CARRIER ROLLER	OK	
	TRACK ROLLER	MINOR OIL LEAK / 油にじみ	
	FRONT IDLER	OK	
	SPROCKET	OK	
NOTE	SWIVEL JOINT COVER MINOR OIL LEAKING. スイベルジョイントカバーにじみあり		

CAB/CNP	CAB/CNP	OK
	ROPS	YES/あり
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	0.9t CRANE, MULTI LEVER

### ATTENTION/注意

\*For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged  
 \*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました