



# GREEN AUCTION

LotNo	5139001	LOCATION	HAKATA-A*
-------	---------	----------	-----------

## CRANE

139th Internet Auction 2026/04/09 ~ 2026/04/10

MAKER	TADANE	YEAR	-	CARRIER HR		CARRIER KM	
MODEL	TM-25Z-1-99	HOUR	-	CHASSIS S/N			
S/N	397349	CHASSIS MODEL					

 DOCUMENT/書類
  UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE	HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	-
	MODEL	-		MAIN WINCH	OK	OUTRIGGER CYLINDER	OK
	S/N	-		AUX WINCH	OK	OUTRIGGER EXTENSION	OK
	COOLANT	OK		BOOM EXTENSION	OK	SWING	OK
	OIL	OK		BOOM HOIST	OK	CONTROL LEVER	OK
	START	OK		NOTE			
	BLOW-BY	NO/なし					
	NOISE	NO/なし					
	NOTE	ENGINE MINOR OIL LEAKING. エンジン油にじみあり					

ELECTRICAL	LIGHT	NG
	WIPER	NG
	HEATER	-
	A/C	-
	BATTERY	DEAD/あがり
	NOTE	

HOOK	CAPACITY	MAIN	2.5 (t)	SUB	- (t)
	NO. OF HOOK	- pcs			
	WIRE LOUPE	OK			
	NOTE	OVER-WIND UP SENSOR DEFECT. 過巻センサー故障			

BOOM	LENGTH	-	m
	CONDITION	OK	
	SHEEVE	OK	
	NOTE		

FORK LIFT	HYDRAULIC	TYPE	-		
		FORK	LENGTH	-	mm
			MAST	LENGTH	-
	LIFT CYLINDER	TILT CYLINDER	-		
		HOIST CYLINDER	-		
		NOTE			

UNDERCARRIAGE	TIRE	SIZE	-
		CONDITION	OK
	SHOE	TYPE	-
		<input type="checkbox"/> W/PAD	OK
		200 mm	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
FRONT IDLER	OK		
SPROCKET	OK		
NOTE			

TRANSMISSION	NO. OF SPEED	F	OK	R	OK
	SHIFT	OK			
	OIL	OK			
	NOTE				

JIB	NO. OF SEC	-	sec
	CONDITION	-	
	NOTE		

CAB	-
SEAT	-
NOTE	

SAFETY DEVICE	MONITOR	OK
	AML	-
	OVER WIND CUT	OK
	NOTE	

BRAKE	FOOT	OK
	PARKING	OK
	NOTE	

REMARK	COVER RUSTY, SCRATCHED. OUTRIGGER CYKINDER OIL LEAKING SLIGHTLY. CYLINDER RODS RUSTY. カバー錆び傷あり アウトリガーシリンダー油漏れ小 一部シリンダーロード錆びあり
--------	---

### ATTENTION/注意

\*For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
 \*別途修理、洗車の費用がかかる場合があります。ご了承くださいませ。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
 \*Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged