



| | | | |
|-------|---------|----------|------------|
| LotNo | 6139005 | LOCATION | YOKOHAMA-E |
|-------|---------|----------|------------|

| | | | |
|-------|------------|------|------|
| MAKER | KIOMATSU | YEAR | 1996 |
| MODEL | GD605A-5E | HOUR | 8754 |
| S/N | G60A5-1612 | | |

139th Internet Auction 2026/04/09 ~ 2026/04/10

DOCUMENT/書類 UNABLE TO TRAVEL(START)/不働車

| | | |
|--------|---------|----------|
| ENGINE | MODEL | 6D125E-2 |
| | S/N | 68579 |
| | COOLANT | OK |
| | OIL | OK |
| | START | OK |
| | BLOW-BY | NO/なし |
| | NOISE | NO/なし |
| | EPA | NO/なし |
| NOTE | | |

| | | |
|--------------|-------|----------------------------|
| TRANSMISSION | GEAR | OK |
| | SHIFT | CLUTCH RETURN NOT SO GOOD. |
| | OIL | OK |
| | NOTE | クラッチ少し戻り悪い |

| | | |
|---------------|---|------------------------------|
| HYDRAULIC | PUMP | OK |
| | LINE | OK |
| | LIFT CYLINDER | OK |
| | TILT CYLINDER | OK |
| | SIDE SHIFT | OK |
| | CENTER SHIFT | PIN NOT REMOVE. NOT CHECKED. |
| | ARTICURATOR | OK |
| | LEANING | OK |
| | CIRCLE DRIVE | OK |
| | LINKAGE | OK |
| CONTROL VALVE | OK | |
| OIL LEVEL | OK | |
| NOTE | CENTER SHIFT CYLINDER MINOR OIL LEAKING. センターシフトシリンダー 油にじみあり センターシフトピン抜けず 未確認 | |

| | | |
|-------|-------------|----|
| FRAME | FRONT FRAME | OK |
| | REAR FRAME | OK |
| | CIRCLE GEAR | OK |
| | PINION GEAR | OK |
| | NOTE | |

| | | |
|--------------|---------|----------------------|
| CABIN/CANOPY | CAB/CNP | OK |
| | ROPS | NO |
| | SEAT | BROKEN/破損 PARTITLLY. |
| | NOTE | |

| | |
|------------|----|
| FRONT AXLE | OK |
| REAR AXLE | OK |
| CENTER PIN | OK |
| NOTE | |

| | | |
|------------|---------------------|----|
| ATTACHMENT | BLADE | OK |
| | RIPPER OR SCARIFIER | OK |
| | NOTE | |

| | | |
|-------|---------|----|
| BRAKE | FOOT | OK |
| | PARKING | OK |
| | NOTE | |

| | | |
|-------|----------------|----------|
| TIRES | SIZE | 14.00-24 |
| | TIRE CONDITION | OK |
| | NOTE | |

| | |
|--------|---|
| REMARK | CABIN LEFT SIDE STEP DEFORM. NUMBER PLATE LIGHT BROKEN. キャビン左側ステップゆがみあり ナンバープレート灯破損 |
|--------|---|

| | | |
|------------|---------|---------------------------|
| ELECTRICAL | LIGHT | OK |
| | WIPER | OK |
| | HEATER | ONLY BLOWER. 送風のみ WEAK/弱い |
| | A/C | - |
| | BATTERY | OK |
| | NOTE | |

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
 *別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
 *Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged
 *2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました