



GREEN AUCTION

FORK LIFT

LotNo	7143003	LOCATION	HAKATA-S*
-------	---------	----------	-----------

MAKER	TCM	YEAR	—	CARRIER HR	—	CARRIER KM	—
MODEL	FG20N6	HOURL	—	CASSIS S/N	—		
S/N	3453342	CASSIS MODEL	—				

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	MINOR OIL LEAK / オイルにじみ		TYPE OF OUTRIGGER	—
	MODEL	H20			MAIN WINCH	—	OUTRIGGER CYLINDER	—	
	S/N	S85977			AUX WINCH	—	OUTRIGGER EXTENSION	—	
	COOLANT	OK			BOOM EXTENSION	—	SWING	—	
	OIL	OK			BOOM HOIST	—	CONTROL LEVER	OK	
	START	OK			NOTE	MAINE PUMP MINOR OIL LEAK / メインポンプオイルにじみ			
	BLOW-BY	NO / なし							
	NOISE	NO / なし							
NOTE	RADIATOR WATER LEAK / ラジエター水漏れ								
HOOK	CAPACITY	MAIN	— (t)	SUB	— (t)	BOOM	LENGTH	— m	
	NO. OF HOOK	— pcs					CONDITION	—	
	WIRE ROPE	—					SHEEVE	—	
	NOTE						NOTE		
TRANSMISSION	NO. OF SPEED	F	1	R	1	JIB	NO. OF SEC	— sec	
	SHIFT	OK					CONDITON	—	
	OIL	OK					NOTE		
	NOTE								
CAB	OK	SAFETY DEVICE	MONITOR	—					
	SEAT		OK	AML	—				
	NOTE			OVER WIND CUT	—				
				NOTE					
FORK LIFT	TYPE	STD		HYDRAULIC	LIFT CYLINDER	SLIDE DOWN BY ITSELF / 自然降下			
	FORK	LENGTH	— mm		TILT CYLINDER	MINOR OIL LEAK / オイルにじみ			
	MAST	LENGTH	3000 mm		HOIST CYLINDER	—			
	NOTE				NOTE				
BRAKE	FOOT	OK		PARKING	OK				
	NOTE								
TIRE	SIZE	F:7.00-12 R:6.00-9		UNDERCARRIAGE	SHOE	TYPE	—		
	CONDITION	REAR TIRE CRACK / リアタイヤひび			W/PAD	— mm			
	PIN BUSH	—			CARRIER ROLLER	—			
	TRACK ROLLER	—			FRONT IDLER	—			
SPROCKET	—		NOTE	STEERING CYLINDER MINOR OIL LEAK / ステアリングシリンダーオイルにじみ					
REMARK									
*PUNCHED NO. UNKNOWN (刻印不明)									

ATTENTION/ 注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました