



GREEN AUCTION

PLATE COMPACTOR

LotNo	9144039	LOCATION	HAKATA-S
-------	---------	----------	----------

SET NAME	PLATE COMPACTOR, MVH
CONTROL NUMBER	3UNITS SET

	UNIT 1	UNIT 2	UNIT 3	UNIT 4	UNIT 5
MODEL	MVH-100AR	MVH-100AR	MVH-308DSC	—	—
S/N	Z7697	Z7685	Z2449	—	—
ENGINE	OK	NG	OK	—	—
BODY	OK	OK	OK	—	—
WORKING	OK	NG	OK	—	—
NOTE		ENGINE MINOR OIL LEAKING. / エンジンにオイルにじみ箇所あり	ENGINE MINOR OIL LEAKING. / エンジンにオイルにじみ箇所あり		
REMARK		UNABLE TO START ENGINE. / エンジン始動しない FUEL NEED REFILL. / 燃料要補充		*NEED RELEASING FEE (出庫料JPY 20,000)	
	UNIT 6	UNIT 7	UNIT 8	UNIT 9	UNIT 10
MODEL	—	—	—	—	—
S/N	—	—	—	—	—
ENGINE	—	—	—	—	—
BODY	—	—	—	—	—
WORKING	—	—	—	—	—
NOTE					
REMARK					

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました