



GREEN AUCTION

## MINI EXCAVATOR

LotNo	1129009	LOCATION	KOBE-N
MAKER	KOMATSU	YEAR	1993
MODEL	PC25-1	HOURL	8001
S/N	5696		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	—
	S/N	—
	COOLANT	NOT ENOUGH / 不足
	OIL	OK
	START	OK
	BLOW-BY	NO / なし
	NOISE	NO / なし
	EPA	NO / なし
	NOTE	OIL & FUEL LEAK / オイルベタ、燃料にじみ

UNDERCARRIAGE	SHOE <input type="checkbox"/> W/PAD	TYPE	RUBBER
	300 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	NG, RIGHT	
	TRACK ROLLER	NG	
	FRONT IDLER		
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	—	
	BUCKET	TYPE	—
		WITHOUT	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	LOOSE / ガタ
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	DEFECT. FRAME CORRODED / 不良、腐食あり
	CONTROL LEVER	DETERIORATED, PLAYED / 劣化、ガタ
	A/C OR HEATER	—
	COMPUTER	—
	MONITOR	BATTERY WARNING LAMP / バッテリー警告灯
	BATTERY	OK
	NOTE	RUSTY, CORRODED / サビ、腐食

CYLINDERS	BOOM	OK
	SWING	MINOR OIL LEAK / オイルにじみ
	ARM	OK
	BUCKET	ROD SCRATCHED / ロッド傷
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	UNDER COVER WET (OIL) / アンダーカバーベタ

ATTACHMENT	—
------------	---

## REMARK

TRAVEL LEVER (RIGHT) BROKEN / 右走行レバー折損  
NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP / 在来船輸出の場合は要洗車

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge. The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
\*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
\*Starting from 1st August 2017, for each successful bid a "Successful Bid Fee" will be charged  
\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました