




GREEN AUCTION

## MANLIFT TRUCK



LotNo
8130013
LOCATION
KOBE-N\*

MAKER	MITSUBISHI	YEAR	2007		
MODEL	PA-FE83DEY (AT-150S-2)	hour	8847	CARRIER HR	—
S/N	FE83DEY- 521829	MILE	75240KM	CASSIS S/N	—

☒ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不動車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	OK	TYPE OF OUTRIGGER	H-TYPE	ELECTRICAL	LIGHT	OK
	MODEL	4M50	—		MAIN WINCH	—	OUTRIGGER CYLINDER	OK		WIPER	OK
	S/N	—	—		AUX WINCH	—	OUTRIGGER EXTENSION	OK		HEATER	OK
	COOLANT	OK	—		BOOM EXTENSION	OK	SWING	OK		A/C	OK
	OIL	OK	—		BOOM HOIST	OK	CONTROL LEVER	OK		BATTERY	OK
	START	OK	—		NOTE					NOTE	
	BLOW-BY	NO / なし	—								
	NOISE	NO / なし	—								
NOTE											

HOOK	CAPACITY	MAIN	—	(t)	SUB	—	(t)	BOOM	LENGTH	—	m
	NO. OF HOOK	—					pcs		CONDITION	OK	
	WIRE ROPE	—					SHEEVE		OK		
	NOTE						NOTE				

TRANSMISSION	NO. OF SPEED	F	5	R	1	JIB	NO. OF SEC	—	sec
	SHIFT	OK					CONDITON	—	
	OIL	OK					NOTE		
	NOTE								

CAB	OK	SAFTY DEVICE	MONITOR	OK	
	SEAT		OK	AML	OK
	NOTE			OVER WIND CUT	OK
				NOTE	

FORK LIFT	HYDRAULIC	TYPE	—	BRAKE	FOOT	OK		
		FORK	LENGTH		—	mm	PARKING	OK
		MAST	LENGTH		—	mm	NOTE	
		LIFT CYLINDER	—					
TILT CYLINDER	—							
HOIST CYLINDER	—							
NOTE								

UNDERCARRIAGE	TIRE	SIZE	225/85R16	REMARK
	CONDITION	OK		
	SHOE	TYPE	—	
	<input type="checkbox"/> W/PAD			
	<input type="checkbox"/> mm			
	PIN BUSH	—		
	CARRIER ROLLER	—		
	TRACK ROLLER	—		
FRONT IDLER	—			
SPROCKET	—			
NOTE				

TADANO AT-150S-2 #HD5513
EXTRA RECYCLING FEE JPY 8,930 / リサイクル料

ATTENTION/ 注意

\*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

\*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

\*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました