



GREEN AUCTION

LotNo	1130008	LOCATION	HAKATA-A
-------	---------	----------	----------

MINI EXCAVATOR

130th Internet Auction 2025/06/12 ~ 2025/06/13

MAKER	YANMAR	YEAR	2011
MODEL	V1017	HOUR	2523
S/N	05249B		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	3TNV70	
	S/N	WS75368	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO/なし	
	NOISE	NO/なし	
	EPA	YES/あり	
	NOTE		

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD	OK	
	630 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	OK	
	ROPS	NO/なし	
	SEAT	OK	
	CONTROL LEVER	OK	
	A/C OR HEATER	-	
	COMPUTER	OK	
	MONITOR	OK	
	BATTERY	OK	
	NOTE		

CYLINDERS	BOOM	OK	
	SWING	OK	
	ARM	OK	
	BUCKET	OK	
	BLADE	OK	
	NOTE		

TURN TABLE	OK	
------------	----	--

CONTROL	HYDRAULIC PUMP	OK	
	TRAVEL	OK	
	SWING	OK	
	CONTROL	OK	
	NOTE		

ATTACHMENT	-	
------------	---	--

REMARK

NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP. 在来船輸出の場合は要洗車

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました