



GREEN AUCTION

LotNo	1130010	LOCATION	HAKATA-A
-------	---------	----------	----------

MAKER	mitsubishi	YEAR	1994
MODEL	MX35	hour	-
S/N	E7D00793		

MINI EXCAVATOR

130th Internet Auction 2025/06/12 ~ 2025/06/13

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	K4E	
	S/N	K4E-48024	
	COOLANT	NEED SUPPLYING/要補充	
	OIL	OK	
	START	OK	
	BLOW-BY	NO/なし	
	NOISE	NO/なし	
	EPA	NO/なし	
	NOTE		

UNDERCARRIAGE	SHOE	TYPE	RUBBER
	<input type="checkbox"/> W/PAD	OK	
	300 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	OFF-SET
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	LOOSE/ガタ(SLIGHTLY/小)
		ARM	LOOSE/ガタ(SLIGHTLY/小)
BUCKET		OK	
NOTE			

CAB/CNP	CAB/CNP	OK
	ROPS	NO/なし
	SEAT	TORN/破れ
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	PANEL DETERIORATED. パネル劣化
	BATTERY	DEAD/あがり
	NOTE	

CYLINDERS	BOOM	OIL LEAKING SEVERELY/オイル漏れ大
	SWING	OK
	ARM	OIL LEAKING SLIGHTLY/オイル漏れ小
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

W/ STD BUCKET
PLATE BROKEN. プレート破損

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました