



GREEN AUCTION

MINI EXCAVATOR

LotNo	1252006	LOCATION	KOBE-N*
MAKER	HITACHI	YEAR	2009
MODEL	ZX30U-3	HOURL	4570
S/N	20402		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	3TNV88-BPHB	
	S/N	B2474	
	COOLANT	OK	
	OIL	OK	
	START	OK	
	BLOW-BY	NO / なし	
	NOISE	NO / なし	
	EPA	YES / あり	
	NOTE		

UNDERCARRIAGE	SHOE	TYPE	STEEL
	☒ W/PAD		
	300 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	SWING
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	OK	
	ROPS	NO / なし	
	SEAT	TORN / 破れ	
	CONTROL LEVER	OK	
	A/C OR HEATER	-	
	COMPUTER	OK	
	MONITOR	OK	
	BATTERY	OK	
	NOTE	LEFT SIDE CONTROL LEVER : OIL LEAK / 左コントロールレバーの下からオイル漏れ	

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

STAMPED SERIAL NUMBER UNKNOWN / 機械打刻未確認

NEED WASHING FOR SHIPPING ON BULK CARRIER SHIP / 在来船輸出の場合は要洗車

ATTENTION/注意 *For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました