



GREEN AUCTION

CRANE

|       |         |          |        |
|-------|---------|----------|--------|
| LotNo | 5252002 | LOCATION | KOBE-N |
|-------|---------|----------|--------|

|       |          |              |           |            |              |            |          |
|-------|----------|--------------|-----------|------------|--------------|------------|----------|
| MAKER | KATO     | YEAR         | 1993      |            |              |            |          |
| MODEL | NK-75M-V | HR           | —         | CARRIER HR | —            | CARRIER KM | 337023KM |
| S/N   | 3010245  | CASSIS MODEL | U-FD3WDA改 | CASSIS S/N | FD3WDA-50059 |            |          |

☒ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

|        |         |                  |       |  |                   |                |    |                     |        |            |         |    |
|--------|---------|------------------|-------|--|-------------------|----------------|----|---------------------|--------|------------|---------|----|
| ENGINE | CARRIER |                  | CRANE |  | HYDRAULIC (CRANE) | PUMP           | OK | TYPE OF OUTRIGGER   | H-TYPE | ELECTRICAL | LIGHT   | OK |
|        | MODEL   | W06E             | —     |  |                   | MAIN WINCH     | OK | OUTRIGGER CYLINDER  | OK     |            | WIPER   | OK |
|        | S/N     | E10611           | —     |  |                   | AUX WINCH      | OK | OUTRIGGER EXTENSION | OK     |            | HEATER  | OK |
|        | COOLANT | OK               | —     |  |                   | BOOM EXTENSION | OK | SWING               | OK     |            | A/C     | OK |
|        | OIL     | OK               | —     |  |                   | BOOM HOIST     | OK | CONTROL LEVER       | OK     |            | BATTERY | OK |
|        | START   | OK               | —     |  |                   | NOTE           |    |                     |        |            | NOTE    |    |
|        | BLOW-BY | NO / なし          | —     |  |                   |                |    |                     |        |            |         |    |
|        | NOISE   | NO / なし          | —     |  |                   |                |    |                     |        |            |         |    |
|        | NOTE    | OIL LEAK / オイル漏れ |       |  |                   |                |    |                     |        |            |         |    |

|              |              |               |           |               |         |      |                |        |           |                |      |               |                                       |      |             |
|--------------|--------------|---------------|-----------|---------------|---------|------|----------------|--------|-----------|----------------|------|---------------|---------------------------------------|------|-------------|
| HOOK         | CAPACITY     | MAIN          | 4.9 (t)   | SUB           | 1.3 (t) | BOOM | LENGTH         | 20.7 m | FORK LIFT | TYPE           | —    | UNDERCARRIAGE | TIRE                                  | SIZE | 225/80R17.5 |
|              | NO. OF HOOK  | 2 pcs         |           |               |         |      | CONDITION      | OK     |           | SHOE           | TYPE |               | —                                     |      |             |
|              | WIRE ROPE    | OK            |           |               |         |      | W/PAD          | — mm   |           | PIN BUSH       | —    |               |                                       |      |             |
|              | NOTE         |               |           |               |         |      | CARRIER ROLLER | —      |           |                |      |               |                                       |      |             |
| TRANSMISSION | NO. OF SPEED | F             | 5         | R             | 1       | JIB  | NO. OF SEC     | — sec  | HYDRAULIC | LIFT CYLINDER  | —    | REMARK        | EXTRA RECYCLING FEE JPY6,710 / リサイクル料 |      |             |
|              | SHIFT        | OK            |           |               |         |      | CONDITON       | —      |           | TILT CYLINDER  | —    |               |                                       |      |             |
|              | OIL          | OK            |           |               |         |      | NOTE           |        |           | HOIST CYLINDER | —    |               |                                       |      |             |
|              | NOTE         | 5M/T          |           |               |         |      | MONITOR        | OK     |           |                |      |               |                                       |      |             |
| CAB          | OK           | SAFETY DEVICE | AML       | OK            | BRAKE   | FOOT | OK             |        |           |                |      |               |                                       |      |             |
|              | SEAT         |               | TORN / 破れ | OVER WIND CUT |         | OK   | PARKING        | OK     |           |                |      |               |                                       |      |             |
|              | NOTE         |               |           | NOTE          |         |      | NOTE           |        |           |                |      |               |                                       |      |             |

ATTENTION/ 注意

\*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.

\*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。

\*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged

\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました