



GREEN AUCTION

LotNo	8252010	LOCATION	HAKATA-A
-------	---------	----------	----------

MANLIFT

152th Tender Auction 2025/06/26 ~ 2025/06/27

MAKER	DENYO	YEAR	2010		
MODEL	HW-600SCR	HOUR	429	CARRIER HR	
S/N	UNKNOWN (1001855)	CHASSIS MODEL		CARRIER KM	

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER		CRANE		HYDRAULIC (CRANE)	PUMP	-	TYPE OF OUTRIGGER	-	
	MODEL	-	-	MAIN WINCH		-	OUTRIGGER CYLINDER	-		
	S/N	-	-	AUX WINCH		-	OUTRIGGER EXTENSION	-		
	COOLANT			BOOM EXTENSION		-	SWING	-		
	OIL			BOOM HOIST		-	CONTROL LEVER	-		
	START			NOTE						
	BLOW-BY									
	NOISE									
	NOTE									
HOOK	CAPACITY	MAIN	- (t)	SUB	- (t)	BOOM	LENGTH	-	m	
	NO. OF HOOK	-					CONDITION	-		
	WIRE LOUPE	-					SHEEVE	-		
	NOTE						NOTE			
TRANSMISSION	NO. OF SPEED	F	-	R	-	JIB	NO. OF SEC	-	sec	
	SHIFT	-					CONDITION	-		
	OIL	-					NOTE			
	NOTE									
CAB	-				SAFETY DEVICE	MONITOR	-			
	SEAT	-				AML	-			
	NOTE					OVER WIND CUT	-			
						NOTE				
FORK LIFT	HYDRAULIC	TYPE	-			BRAKE	FOOT	-		
		FORK	LENGTH	-			mm	PARKING	-	
			-				NOTE			
		MAST	LENGTH	6000			mm			
			-							
LIFT CYLINDER	-									
TILT CYLINDER	-									
HOIST CYLINDER	-									
NOTE										
REMARK										
TRAVELING NOT TESTED, DUE TO POOR CHARGE STATE. UNDER CARRIAGE DIRTY. SERIAL PLATE MISSING. 充電不足のため走行テスト未実施 足回り汚れあり シリアルプレート欠損										

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a “ Successful Bid Fee” will be charged