



GREEN AUCTION

LotNo	1252022	LOCATION	HAKATA-A
MAKER	KUBOTA	YEAR	-
MODEL	U-35-5	HOUR	2681
S/N	70082		

MINI EXCAVATOR

152th Tender Auction 2025/06/26 ~ 2025/06/27

☐ DOCUMENT/書類 ☒ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	D1703
	S/N	D7S2098
	COOLANT	LEAKING/漏れ
	OIL	OK
	START	NG
	BLOW-BY	NO/なし
	NOISE	NO/なし
	EPA	NO/なし
	NOTE	WHITE SMOKE. STARTER DEFECT. 白煙あり セル不良

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD	OK	
	300 mm		
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE	STAIN. CAUTION, NEED WASHING. 汚れあり 洗車注意	

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD, SLOPE
		OK	
	BLADE	OK	
	PINS	BOOM	OK
		ARM	LOOSE/ガタ(SLIGHTLY/小)
		BUCKET	LOOSE/ガタ(SLIGHTLY/小)
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO/なし
	SEAT	TORN/破れ
	CONTROL LEVER	OK
	A/C OR HEATER	-
	COMPUTER	OK
	MONITOR	OK
	BATTERY	DEAD/あがり
	NOTE	BATTERY CHARGING, BUT WONT TURN ON. バッテリー充電しても電源入らない

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

REMARK

ELECTRICAL SYSTEM DEFECT, SERIAL PLATE UNKNOWN, UNABLE TO START ENGINE 電気系エンジン不調 シリアルプレート不明 エンジン不動

*NEED REPAIR 要修理

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged
*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました