



GREEN AUCTION

MANLIFT

|       |         |          |            |
|-------|---------|----------|------------|
| LotNo | 8131004 | LOCATION | YOKOHAMA-E |
|-------|---------|----------|------------|

|       |         |              |      |            |   |            |   |
|-------|---------|--------------|------|------------|---|------------|---|
| MAKER | MAEDA   | YEAR         |      |            |   |            |   |
| MODEL | HF090-3 | HOUR         | 3806 | CARRIER HR | — | CARRIER KM | — |
| S/N   | 9HF3511 | CASSIS MODEL | —    | CASSIS S/N | — |            |   |

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

|        |         |         |   |                   |                |    |                     |    |            |         |    |
|--------|---------|---------|---|-------------------|----------------|----|---------------------|----|------------|---------|----|
| ENGINE | CARRIER | CRANE   |   | HYDRAULIC (CRANE) | PUMP           | OK | TYPE OF OUTRIGGER   | —  | ELECTRICAL | LIGHT   | —  |
|        | MODEL   | S3L2    | — |                   | MAIN WINCH     | —  | OUTRIGGER CYLINDER  | —  |            | WIPER   | —  |
|        | S/N     | —       | — |                   | AUX WINCH      | —  | OUTRIGGER EXTENSION | —  |            | HEATER  | —  |
|        | COOLANT | OK      | — |                   | BOOM EXTENSION | OK | SWING               | OK |            | A/C     | —  |
|        | OIL     | OK      | — |                   | BOOM HOIST     | OK | CONTROL LEVER       | OK |            | BATTERY | OK |
|        | START   | OK      | — |                   | NOTE           |    |                     |    |            | NOTE    |    |
|        | BLOW-BY | NO / なし | — |                   |                |    |                     |    |            |         |    |
|        | NOISE   | NO / なし | — |                   |                |    |                     |    |            |         |    |
| NOTE   | EPA     |         |   |                   |                |    |                     |    |            |         |    |

|      |             |      |   |     |     |   |        |      |           |   |   |
|------|-------------|------|---|-----|-----|---|--------|------|-----------|---|---|
| HOOK | CAPACITY    | MAIN | — | (t) | SUB | — | (t)    | BOOM | LENGTH    | — | m |
|      | NO. OF HOOK | —    |   |     |     |   | pcs    |      | CONDITION | — |   |
|      | WIRE ROPE   | —    |   |     |     |   | SHEEVE |      | —         |   |   |
|      | NOTE        |      |   |     |     |   | NOTE   |      |           |   |   |

|              |              |   |   |   |          |     |            |   |     |
|--------------|--------------|---|---|---|----------|-----|------------|---|-----|
| TRANSMISSION | NO. OF SPEED | F | — | R | —        | JIB | NO. OF SEC | — | sec |
|              | SHIFT        | — |   |   | CONDITON |     | —          |   |     |
|              | OIL          | — |   |   | NOTE     |     |            |   |     |
|              | NOTE         |   |   |   |          |     |            |   |     |

|      |   |               |               |   |
|------|---|---------------|---------------|---|
| CAB  | — | SAFETY DEVICE | MONITOR       | — |
| SEAT | — |               | AML           | — |
| NOTE |   |               | OVER WIND CUT | — |
|      |   |               | NOTE          |   |

|           |                |        |        |    |       |      |         |   |
|-----------|----------------|--------|--------|----|-------|------|---------|---|
| FORK LIFT | HYDRAULIC      | TYPE   | —      |    | BRAKE | FOOT | OK      |   |
|           |                | FORK   | LENGTH | —  |       | mm   | PARKING | — |
|           | MAST           | LENGTH | —      | mm |       | NOTE |         |   |
|           |                |        |        |    |       |      |         |   |
| HYDRAULIC | LIFT CYLINDER  | —      | NOTE   |    |       |      |         |   |
|           | TILT CYLINDER  | —      |        |    |       |      |         |   |
|           | HOIST CYLINDER | —      |        |    |       |      |         |   |
|           |                |        |        |    |       |      |         |   |

|                |           |                                |      |        |      |        |
|----------------|-----------|--------------------------------|------|--------|------|--------|
| UNDERCARRIAGE  | TIRE      | SIZE                           | —    | REMARK | 9.1M |        |
|                | CONDITION | —                              |      |        |      |        |
|                | SHOE      | <input type="checkbox"/> W/PAD | TYPE |        |      | RUBBER |
|                | 300       | mm                             | OK   |        |      |        |
| PIN BUSH       | —         |                                |      |        |      |        |
| CARRIER ROLLER | OK        |                                |      |        |      |        |
| TRACK ROLLER   | OK        |                                |      |        |      |        |
| FRONT IDLER    | OK        |                                |      |        |      |        |
| SPROCKET       | OK        |                                |      |        |      |        |
| NOTE           |           |                                |      |        |      |        |

ATTENTION/ 注意

\*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
\*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
\*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました