



# GREEN AUCTION

LotNo	2131013	LOCATION	YOKOHAMA-E*
-------	---------	----------	-------------

MAKER	SUMITOMO	YEAR	2018
MODEL	SH200-7	HOUR	7525
S/N	SC1406		

## EXCAVATOR

131th Tender Auction 2025/07/10 ~ 2025/07/11

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	4HK1X
	S/N	774908
	COOLANT	OK
	OIL	NOT ENOUGH/少ない
	START	OK
	BLOW-BY	NO/なし
	NOISE	NO/なし
	EPA	YES/あり
	NOTE	ENGINE SYSTEM FAIL INDICATING. WORKING IS OK. 液晶「エンジン系統異常」表示あり 動き問題なし

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input type="checkbox"/> W/PAD		
	<input checked="" type="checkbox"/> mm		RUSTY, CORRODED. サビ・腐食あり
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
		OK	
	ARM	TYPE	STD
		OK	
	PIPING	-	
	BUCKET	TYPE	STD
		OK	
	BLADE	-	
	PINS	BOOM	OK
		ARM	OK
		BUCKET	LOOSE/ガタ
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	-
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	OK
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

CYLINDERS	BOOM	OK
	SWING	OK
	ARM	OK
	BUCKET	OK
	BLADE	-
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	

ATTACHMENT	-
------------	---

### REMARK

ENGINE SYSTEM FAIL INDICATING. WORKING IS OK. 液晶「エンジン系統異常」表示あり 動き問題なし
---

### ATTENTION/注意

\*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
\*別途修理、洗車の費用がかかる場合があります。ご了承くださいませようお願いします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
\*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged  
\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました