



GREEN AUCTION

## EXCAVATOR

LotNo	2132003	LOCATION	KOBE-N
MAKER	KOBELCO	YEAR	2009
MODEL	SK70SR-2	HOURL	7323
S/N	YT05-16102		

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	MODEL	4LE2X
	S/N	—
	COOLANT	OK
	OIL	OK
	START	OK
	BLOW-BY	YES / あり (SLIGHTLY/小)
	NOISE	NO / なし
	EPA	YES / あり
	NOTE	MINOR OIL LEAK / オイルにじみ

UNDERCARRIAGE	SHOE	TYPE	STEEL
	<input checked="" type="checkbox"/> W/PAD		
	450 mm	OK	
	PIN BUSH	OK	
	CARRIER ROLLER	OK	
	TRACK ROLLER	OK	
	FRONT IDLER	OK	
	SPROCKET	OK	
	NOTE		

FRONT ATTACHMENT	BOOM	TYPE	STD
			OK
	ARM	TYPE	STD
			OK
	PIPING		—
	BUCKET	TYPE	STD
			OK
	BLADE		WORN / 摩耗
	PINS	BOOM	OK
		ARM	OK
		BUCKET	OK
	NOTE		

CAB/CNP	CAB/CNP	OK
	ROPS	NO / なし
	SEAT	OK
	CONTROL LEVER	OK
	A/C OR HEATER	COOLER DOES NOT WORK / 冷えない
	COMPUTER	OK
	MONITOR	OK
	BATTERY	OK
	NOTE	

CYLINDERS	BOOM	OK
	SWING	—
	ARM	OK
	BUCKET	OK
	BLADE	OK
	NOTE	

TURN TABLE	OK
------------	----

CONTROL	HYDRAULIC PUMP	OK
	TRAVEL	OK
	SWING	OK
	CONTROL	OK
	NOTE	4WAY MULTI LEVER / 4WAYマルチレバー

ATTACHMENT	—
------------	---

REMARK
MACHINE ENGRAVING NEEDS TO BE CHECKED / 本体刻印要確認 1.4T ARM CRANE / クレーン付き

ATTENTION/注意 \*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.  
\*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。  
\*Starting from 1st August 2017,for each successful bid a "Successful Bid Fee" will be charged  
\*2017年8月1日より各落札ロットごとに「落札手数料」が必須となりました