



GREEN AUCTION

LotNo	7132007	LOCATION	YOKOHAMA-E
-------	---------	----------	------------

FORKLIFT

132th Internet Auction 2025/08/21 ~ 2025/08/22

MAKER	KOMATSU	YEAR	2014				
MODEL	FE25-1	HOUR	647	CARRIER HR		CARRIER KM	1247
S/N	300135	CHASSIS MODEL	8274-300135	CHASSIS S/N			

☐ DOCUMENT/書類 ☐ UNABLE TO TRAVEL(START)/不働車

ENGINE	CARRIER	CRANE		HYDRAULIC (CRANE)	PUMP	-	TYPE OF OUTRIGGER	-
	MODEL	-	-		MAIN WINCH	-	OUTRIGGER CYLINDER	-
	S/N	-	-		AUX WINCH	-	OUTRIGGER EXTENSION	-
	COOLANT	-	-		BOOM EXTENSION	-	SWING	-
	OIL	-	-		BOOM HOIST	-	CONTROL LEVER	-
	START	-	-		NOTE			
	BLOW-BY	-	-					
	NOISE	-	-					
	NOTE	ELECTRIC TYPE バッテリー仕様						

HOOK	CAPACITY	MAIN	- (t)	SUB	- (t)
	NO. OF HOOK	- pcs			
	WIRE LOUPE	-			
	NOTE				

BOOM	LENGTH	- m	
	CONDITION	-	
	SHEEVE	-	
	NOTE		

TRANSMISSION	NO. OF SPEED	F	-	R	-
	SHIFT	-			
	OIL	-			
	NOTE				

JIB	NO. OF SEC	- sec	
	CONDITION	-	
	NOTE		

SAFETY DEVICE	MONITOR	-
	AML	-
	OVER WIND CUT	-
	NOTE	

FORK LIFT	TYPE	STD	
		FORK	LENGTH 1200 mm
	MAST	LENGTH 4300 mm	
		OK	
HYDRAULIC	LIFT CYLINDER	OK	
	TILT CYLINDER	OK	
	HOIST CYLINDER	-	
	NOTE		

BRAKE	FOOT	-
	PARKING	-
	NOTE	

TIRE	SIZE	23x9-10/18x7-8	
	CONDITION	OK	
	SHOE	TYPE	-
	☐ W/PAD		
UNDERCARRIAGE	- mm		
	PIN BUSH	-	
	CARRIER ROLLER	-	
	TRACK ROLLER	-	
	FRONT IDLER	-	
	SPROCKET	-	
	NOTE		

REMARK			
2.15t, W/CHARGER			
BODY SCRATCHED ERROR"203"INDICATING. NO FULL OPERATING TEST.DUR TO LOW BATTERY. エラーコード"203"あり バッテリー少ないため動作未確認			

ATTENTION/注意

*For unit required washing or repair, extra fee will be charge.The purpose of this condition report is just for reference, there is no warranty to the accuracy of the information.
*別途修理、洗車の費用がかかる場合があります。ご了承くださいますようお願いいたします。この査定書は、あくまで参考資料です。実際の機械のコンディションを保障するものではありません。
*Starting from 1st August 2017,for each successful bid a " Successful Bid Fee" will be charged